

Repair Order Detail - Customer Copy

RO Number: 465548

RO Status: CLOSED

Customer: DAN PERKINS SUBARU

Phone(s): Contact: (203)882-5686

Vehicle: 4S4BTAPC6M3138096

Main: (203)882-5686

2021 OTBK

BLACK

NOEMAIL.EMAIL@EMAIL.COM

Cell: (914)384-2574

Mileage: 54,098

Service advisor: 397

Tag number: T3138096

Payment type: CASH

Promised time: 08:00 PM

Promised date: 01/27/2026

Waiter: No

Estimate: 0.00

~~~~~  
A SAFETY CHECK & OIL AND FILTER CHANGE AND CHECK ALL FLUIDS  
SCLOF IUC SAFETY CHECK & OIL AND FILTER CHANGE AND CHECK ALL FLUIDS N/C

Tech(s): 98

15208AA21A

SOA635045

803916010

1 ELEM CP-OIL FLTR

6 OIL 0W20 SYNTH

1 GASKET

Pts: 0.00 Lbr: 0.00 Other: 0.00 Total Line A: 0.00

Story: 54098 PERFORM LUBE OIL AND FILTER CHANGE WITH GENUINE SUBARU PARTS AND FLUIDS

~~~~~  
B WRA24 - ODS SENSOR FAILURE, Power Seat - OPEN PARTS LIMITED
100579 W WRA-24 ODS SENSOR SET R&R N/C

Tech(s): 98

SOA635183

1 WRA24- POWER HARDWARE KIT

98329AN00A

1 WRA-24-ODS SENSOR KIT

Pts: 0.00 Lbr: 0.00 Other: 0.00 Total Line B: 0.00

Story: 54098 REPLACED PS SEAT ODS SENOSRS AND REZEROED SEAT DONE

~~~~~  
C DMV SHEET  
DMV IUC DMV PASS N/C

Tech(s): 98

Pts: 0.00 Lbr: 0.00 Other: 0.00 Total Line C: 0.00

~~~~~  
D** SUBARU CABIN AIR FILTER \$94.99
CABIN IUC SUBARU CABIN AIR FILTER \$94.99 N/C

Tech(s): 98

72880FL00A

1 FILTER

Pts: 0.00 Lbr: 0.00 Other: 0.00 Total Line D: 0.00

~~~~~  
E\*\* SUBARU ENGINE AIR FILTER  
AIR IUC SUBARU ENGINE AIR FILTER N/C

Tech(s): 98

16546AA16A

1 ELEMENT AIR CLEANER

Pts: 0.00 Lbr: 0.00 Other: 0.00 Total Line E: 0.00

~~~~~  
F** FRONT WIPER REPLACEMENT (2X)
WIPER IUC FRONT WIPER REPLACEMENT (2X) N/C

Repair Order Detail - Customer Copy

RO Number: 465548

RO Status: CLOSED

Customer: DAN PERKINS SUBARU

Phone(s): Contact: (203)882-5686

Main: (203)882-5686

NOEMAIL.EMAIL@EMAIL.COM

Cell: (914)384-2574

Vehicle: 4S4BTAPC6M3138096

2021 OTBK

BLACK

Mileage: 54,098

Service advisor: 397

Tag number: T3138096

Payment type: CASH

Promised time: 08:00 PM

Promised date: 01/27/2026

Waiter: No

Estimate: 0.00

~~~~~  
Tech(s): 98

SOA591B726

1 PB001826 26" BEAM

N/C

WIPER B

SOA591B718

1 PB001821 18" BEAM

N/C

WIPER B

Pts: 0.00 Lbr: 0.00 Other: 0.00 Total Line F: 0.00  
~~~~~

G** REAR WIPER REPLACEMENT

WIPERR

IUC

REAR WIPER

REPLACEMENT

N/C

Tech(s): 98

SOA591R616

1 PB001822 16" REAR

N/C

WIPER B

Pts: 0.00 Lbr: 0.00 Other: 0.00 Total Line G: 0.00
~~~~~

H\*\* CUSTOMER STATES REMOVE AND REPLACE BOTH FRONT LOWER CONTROL ARM BUSHINGS

OO

IUC

TECH REMOVED AND  
REPLACED BOTH FRONT  
LOWER CONTROL ARM  
BUSHINGS

N/C

Tech(s): 98

20204AG030

2 BUSHING TRANSVERSE

N/C

LINK F

20204FL020

2 BUSHING TRANSVERSE

N/C

LINK R

051030300

2 COTTER PIN

N/C

Pts: 0.00 Lbr: 0.00 Other: 0.00 Total Line H: 0.00  
~~~~~

I** 4 WHEEL ALIGNMENT. INSPECT/ADJUST CASTER, CAMBER & TOE, INSPECT
SUSPENSION & STEERING. TECH ROAD TESTED.

ALIGN

IUC

4 WHEEL ALIGNMENT.
INSPECT/ADJUST
CASTER, CAMBER & TOE,
INSPECT SUSPENSION &
STEERING. TECH ROAD
TESTED.

N/C

Tech(s): 98

Pts: 0.00 Lbr: 0.00 Other: 0.00 Total Line I: 0.00

Story: 54098 PERFORM FULL FOUR WHEEL ALIGNMENT AND PERFORM
QUALITY ROAD TEST
~~~~~

J\*\* CUSTOMER STATES REPLACE BATTERY IN FOB

FOB

IUC

CUSTOMER STATES

N/C

# Repair Order Detail - Customer Copy

RO Number: 465548

RO Status: CLOSED

Customer: DAN PERKINS SUBARU

[NOEMAIL.EMAIL@EMAIL.COM](mailto:NOEMAIL.EMAIL@EMAIL.COM)

Phone(s): Contact: (203)882-5686

Main: (203)882-5686

Cell: (914)384-2574

Vehicle: 4S4BTAPC6M3138096

2021 OTBK

BLACK

Mileage: 54,098

Payment type: CASH

Waiter: No

Service advisor: 397

Promised time: 08:00 PM

Estimate: 0.00

Tag number: T3138096

Promised date: 01/27/2026

~~~~~  
REPLACE BATTERY IN
FOB

Tech(s): 98

2032

1 BATTERY

N/C

Pts: 0.00 Lbr: 0.00 Other: 0.00 Total Line J: 0.00
~~~~~

Customer Pay

Labor

0.00

Parts

0.00

Lube

0.00

Sublet

0.00

Miscellaneous/Shop Charge

0.00

Deductible

0.00

Total Charges

0.00

Less Insurance/Adjustment

0.00

Sales Tax

0.00

Total

0.00