

Repair Order Detail - Customer Copy

RO Number: 470180

RO Status: CLOSED

Customer:

Phone(s): Contact: (203)882-5686

Main:

Cell:

Vehicle: JF2SJABC4FH526369

2015 FOREST

SILVER

Mileage: 135,305

Payment type: CASH

Waiter: No

Service advisor: 290

Promised time: 08:00 PM

Estimate: 0.00

Tag number: T369

Promised date: 04/08/2026

~~~~~  
**A** CHECK AND ADVISE AND REPORT  
 SCLOF IUC SAFETY CHECK & OIL N/C  
 AND FILTER CHANGE AND  
 CHECK ALL FLUIDS

Tech(s): 29  
 15208AA21A 1 ELEM CP-OIL FLTR N/C  
 SOA635045 6 OIL 0W20 SYNTH N/C  
 803916010 1 GASKET N/C

Pts: 0.00 Lbr: 0.00 Other: 0.00 Total Line A: 0.00  
 Story: 135305 150 performed safety

~~~~~  
B DMV SHEET
 DMV IUC PASS N/C

Tech(s): 29

Pts: 0.00 Lbr: 0.00 Other: 0.00 Total Line B: 0.00

~~~~~  
**C** NO OPEN RECALL AS OF TODAY  
 NR IUC NO OPEN RECALL AS OF N/C  
 TODAY

Tech(s): 29

Pts: 0.00 Lbr: 0.00 Other: 0.00 Total Line C: 0.00

~~~~~  
D** FRONT WIPER REPLACEMENT (2X)
 WIPER IUC FRONT WIPER N/C
 REPLACEMENT (2X)

Tech(s): 29
 SOA591U526 1 26" HYBRID WIPER BLADE N/C
 (D

SOA591U517 1 17" HYBRID WIPER BLADE N/C
 (P

Pts: 0.00 Lbr: 0.00 Other: 0.00 Total Line D: 0.00
 Story: 135305 20 replaced front wipers

~~~~~  
**E\*\*** REAR WIPER REPLACEMENT  
 WIPERR IUC REAR WIPER N/C  
 REPLACEMENT

Tech(s): 29  
 SOA591R614 1 14" REAR WIPER BLADE N/C

Pts: 0.00 Lbr: 0.00 Other: 0.00 Total Line E: 0.00  
 Story: 135305 10 replaced rear wiper

~~~~~  
F** SUBARU CABIN AIR FILTER \$94.99
 CABIN IUC SUBARU CABIN AIR N/C
 FILTER \$94.99

Tech(s): 29

Repair Order Detail - Customer Copy

RO Number: 470180

RO Status: CLOSED

Customer:

Phone(s): Contact: (203)882-5686
 Vehicle: JF2SJABC4FH526369

Main: 2015 FOREST SILVER

Cell:

Mileage: 135,305
 Service advisor: 290
 Tag number: T369

Payment type: CASH
 Promised time: 08:00 PM
 Promised date: 04/08/2026

Waiter: No
 Estimate: 0.00

~~~~~  
 72880FG000 1 FILTER N/C  
 Pts: 0.00 Lbr: 0.00 Other: 0.00 Total Line F: 0.00

G\*\* SUBARU ENGINE AIR FILTER N/C  
 AIR IUC SUBARU ENGINE AIR FILTER

Tech(s): 29  
 16546AA12A 1 ELEMENT AIR CLEANER N/C  
 Pts: 0.00 Lbr: 0.00 Other: 0.00 Total Line G: 0.00

H\*\* CUSTOMER STATES REPLACE DRIVE BELT N/C  
 BELT IUC CUSTOMER STATES REPLACE DRIVE BELT

Tech(s): 29  
 23780AA130 1 V BELT N/C  
 Pts: 0.00 Lbr: 0.00 Other: 0.00 Total Line H: 0.00  
 Story: 135305 70 replaced drive belt

I\*\* TECH NOTED NEED TO REPLACE THE DR-AXLE SEAL N/C  
 00 IUC REPLACE THE DR-AXLE SEAL

Tech(s): 29  
 806735290 1 OIL SEAL-35X50X9 N/C  
 Pts: 0.00 Lbr: 0.00 Other: 0.00 Total Line I: 0.00  
 Story: 135305 200 replaced driver axle seal

J\*\* TECH NOTED DR-FRONT CONTROL ARM BOLT NEEDS TO BE REPLACE N/C  
 00 IUC TECH NOTED REPLACE THE DR-CONTROL ARM BOLT

Tech(s): 29  
 901000396 1 BOLT FLG 12X82.5 N/C  
 902350030 1 SELF LOCK NUT M12 N/C  
 Pts: 0.00 Lbr: 0.00 Other: 0.00 Total Line J: 0.00  
 Story: 135305 replaced driver control arm bolt

K\*\* 4 WHEEL ALIGNMENT. INSPECT/ADJUST CASTER, CAMBER & TOE, INSPECT N/C  
 SUSPENSION & STEERING. TECH ROAD TESTED.  
 ALIGN IUC 4 WHEEL ALIGNMENT. INSPECT/ADJUST CASTER, CAMBER & TOE, INSPECT SUSPENSION & STEERING. TECH ROAD TESTED.

# Repair Order Detail - Customer Copy

RO Number: 470180

RO Status: CLOSED

**Customer:**

Phone(s): Contact: (203)882-5686  
 Vehicle: JF2SJABC4FH526369

Main: 2015 FOREST SILVER

Cell:

Mileage: 135,305  
 Service advisor: 290  
 Tag number: T369

Payment type: CASH  
 Promised time: 08:00 PM  
 Promised date: 04/08/2026

Waiter: No  
 Estimate: 0.00

~~~~~  
 Tech(s): 29
 Pts: 0.00 Lbr: 0.00 Other: 0.00 Total Line K: 0.00
 Story: 135305 100 PERFORM FULL FOUR WHEEL ALIGNMENT AND PERFORM
 QUALITY ROAD TEST
 ~~~~~

L\*\* REAR BRAKE SERVICE: PADS & ROTORS  
 RBJR IUC REAR BRAKE SERVICE: PADS & ROTORS N/C

Tech(s): 29  
 26696FJ000 1 BRAKE PAD KIT REAR N/C  
 26700FJ000 2 BRAKE DISC R N/C  
 Pts: 0.00 Lbr: 0.00 Other: 0.00 Total Line L: 0.00  
 Story: 135305 200 replaced rear rotors and pads  
 ~~~~~

M** TECH NOTED HEATSHIED RATTLE
 00 IUC REPAIRED HEAT SHIELD N/C

Tech(s): 29
 Pts: 0.00 Lbr: 0.00 Other: 0.00 Total Line M: 0.00
 Story: 135305 50 resecured heat shields
 ~~~~~

N\*\* TECH NOTED LIC PLATE BULB NEEDS TO BE REPLACE  
 00 IUC REPLACE THE LIC PLATE BULB N/C

Tech(s): 29  
 784920080 1 BULB N/C  
 Pts: 0.00 Lbr: 0.00 Other: 0.00 Total Line N: 0.00  
 Story: 135305 20 replaced driver side license plate bulb  
 ~~~~~

Customer Pay	
Labor	0.00
Parts	0.00
Lube	0.00
Sublet	0.00
Miscellaneous/Shop Charge	0.00
Deductible	0.00
Total Charges	0.00
Less Insurance/Adjustment	0.00
Sales Tax	0.00
Total	0.00