

# Repair Order Detail - Customer Copy

RO Number: 463867

RO Status: CLOSED

Customer: DAN PERKINS SUBARU

Phone(s): Contact: (203)882-5686

Vehicle: JF2GTAECXPH275922

Main: (203)882-5686

2023 CRTK

WHITE

NOEMAIL@EMAIL.COM

Cell:

Mileage: 24,979

Payment type: CASH

Service advisor: 290

Promised time: 08:00 PM

Tag number: T922

Promised date: 12/31/2025

Waiter: No

Estimate: 0.00

## A SAFETY CHECK & OIL AND FILTER CHANGE AND CHECK ALL FLUIDS

SCLOF IUC SAFETY CHECK & OIL  
AND FILTER CHANGE AND  
CHECK ALL FLUIDS

N/C

Tech(s): 270  
15208AA21A 1 ELEM CP-OIL FLTR  
SOA635045 6 OIL 0W20 SYNTH  
803916010 1 GASKET

N/C

N/C

N/C

Pts: 0.00 Lbr: 0.00 Other: 0.00 Total Line A: 0.00

Story: 24979 PERFORM LUBE OIL AND FILTER CHANGE WITH GENUINE  
SUBARU PARTS AND FLUIDS

## B DMV SHEET

DMV IUC PASS

N/C

Tech(s): 270

Pts: 0.00 Lbr: 0.00 Other: 0.00 Total Line B: 0.00

## C NO OPEN RECALL AS OF TODAY

NR IUC NO OPEN RECALL AS OF  
TODAY

N/C

Tech(s): 270

Pts: 0.00 Lbr: 0.00 Other: 0.00 Total Line C: 0.00

## D CERTIFIED PRE-OWNED VEHICLE INSPECTION

CPO IUC CERTIFIED PRE-OWNED  
VEHICLE INSPECTION

N/C

Tech(s): 270

Pts: 0.00 Lbr: 0.00 Other: 0.00 Total Line D: 0.00

Story: 24979 cpo completed

## E\*\* SUBARU CABIN AIR FILTER \$94.99

CABIN IUC SUBARU CABIN AIR  
FILTER \$94.99

N/C

Tech(s): 270

Pts: 0.00 Lbr: 0.00 Other: 0.00 Total Line E: 0.00

Story: 24979 replaced filter

## F\*\* SUBARU ENGINE AIR FILTER

AIR IUC SUBARU ENGINE AIR  
FILTER

N/C

Tech(s): 270

Pts: 0.00 Lbr: 0.00 Other: 0.00 Total Line F: 0.00

16546AA210 1 PB001983 ELEMENT-AIR  
CLNR

N/C

# Repair Order Detail - Customer Copy

RO Number: 463867

RO Status: CLOSED

Customer: DAN PERKINS SUBARU  
Phone(s): Contact: (203)882-5686  
Vehicle: JF2GTAECXPH275922

Main: (203)882-5686  
2023 CRTK WHITE

NOEMAIL@EMAIL.COM  
Cell:

Mileage: 24,979  
Service advisor: 290  
Tag number: T922

Payment type: CASH  
Promised time: 08:00 PM  
Promised date: 12/31/2025

Waiter: No  
Estimate: 0.00

Story: 24979 replaced filter

G\*\* FRONT WIPER REPLACEMENT (2X)  
WIPER IUC FRONT WIPER  
REPLACEMENT (2X)

Tech(s): 270  
SOA591B726 1 PB001826 26" BEAM  
WIPER B  
SOA591B716 1 16" BEAM WIPER BLADE  
(PAS)  
SOA591R612 1 12" REAR WIPER BLADE  
N/C  
Pts: 0.00 Lbr: 0.00 Other: 0.00 Total Line G: 0.00  
Story: 24979 replaced wipers

H\*\* FRONT BRAKE SERVICE: PADS & RESURFACED ROTORS  
FBJ IUC FRONT BRAKE SERVICE:  
PADS & RESURFACED  
ROTORS

Tech(s): 270  
26298FL001 1 SHIM KIT F  
26296FL032 1 PAD KIT F  
26300FL010 2 BRAKE DISK FRONT  
SOA635334 1 DOT 3 BRAKE FLUID  
N/C  
Pts: 0.00 Lbr: 0.00 Other: 0.00 Total Line H: 0.00  
Story: 24979 fbjr completed

I\*\* REAR BRAKE SERVICE: PADS & RESURFACED ROTORS  
RBJ IUC REAR BRAKE SERVICE:  
PADS & RESURFACED  
ROTORS

Tech(s): 270  
26696FJ000 1 BRAKE PAD KIT REAR  
26700FJ000 2 BRAKE DISC R  
T20 1 BRAKEKLEEN NON-CHLOR  
26642AE000 2 PLUG BRAKE DRUM  
N/C  
Pts: 0.00 Lbr: 0.00 Other: 0.00 Total Line I: 0.00  
Story: 24979 rbjr completed

J\*\* PERFORM TIRE ROTATION  
TR IUC PERFORM TIRE ROTATION

Tech(s): 270  
Pts: 0.00 Lbr: 0.00 Other: 0.00 Total Line J: 0.00  
Story: 24979 trb completed

# Repair Order Detail - Customer Copy

RO Number: 463867

RO Status: CLOSED

Customer: DAN PERKINS SUBARU  
Phone(s): Contact: (203)882-5686  
Vehicle: JF2GTAECXPH275922

Main: (203)882-5686  
2023 CRTK WHITE

NOEMAIL@EMAIL.COM  
Cell:

Mileage: 24,979  
Service advisor: 290  
Tag number: T922

Payment type: CASH  
Promised time: 08:00 PM  
Promised date: 12/31/2025

Waiter: No  
Estimate: 0.00

K\*\* TECH NOTED RIGHT REAR LINER IS TORN

00 IUC INSTALLED COVER AND  
CLIPS

N/C

Tech(s): 270

57731FL500

1 COVER BUMPER SIDE REAR  
RH

N/C

J101SFL620

1 SPLASH GUARD KIT REAR

N/C

J101SFL710

1 SPLASH GUARD HARDWARD  
KIT

N/C

Pts: 0.00 Lbr: 0.00 Other: 0.00 Total Line K: 0.00

Story: 24979 replaced all torn liner pieces in right rear

L\*\* TECH NOTED RIGHT REAR STRUT BOOT TORN

00 IUC REMOVED AND INSTALLED  
NEW STRUT COVER RIGHT  
REAR.

N/C

Tech(s): 270

Pts: 0.00 Lbr: 0.00 Other: 0.00 Total Line L: 0.00

Story: 24979 removed right rear strut and replaced broken dust  
cover

## Customer Pay

Labor	0.00
Parts	0.00
Lube	0.00
Sublet	0.00
Miscellaneous/Shop Charge	0.00
Deductible	0.00
Total Charges	0.00
Less Insurance/Adjustment	0.00
Sales Tax	0.00
Total	0.00