Repair Order Detail - Customer Copy

RO Number: 461868 RO Status: CLOSED

Customer: DAN PERKINS SUBARU

Main: (203)882-5686

NOEMAIL@EMAIL.COM Cell:

Phone(s): Contact: (203)882-5686 Vehicle: 4S3GTAC64K3738008

2019 IMPR

AF72811

Mileage: 92,222

Payment type: CASH

Waiter: No

SILVER

Service advisor: 290

Promised time: 08:00 PM

Estimate: 0.00

Tag number: T008 Promised date: 11/26/2025

		AND ADVISE			~~~~~~	~~~~~~	
S	CLOF	IUC		CHECK & OIL TER CHANGE ANI			N/C
				ALL FLUIDS	J		
	Tech(s):	29	01120117				
	15208A			1 ELEM CP-OI			N/C
	SOA635			6 OIL 0W20 SY	/NTH		N/C
Pts:	8039160			1 GASKET 0.00 Other:	0.00	Total Line A:	N/C 0.00
		150 performe		o.oo ouror.	0.00	Total Elilo7t.	0.00
~~~ B	DMV SI	.~~~~~~~ <i>.</i> HEET	~~~~~	~~~~~~~	~~~~~~	~~~~~~	~~~~~
D	MV	IUC	PASS				N/C
<b>5</b> .	Tech(s):	29		0.00 04		<b>-</b>	2.22
Pts:	ry: 92222	0.00 Lbr:		0.00 Other:	0.00	Total Line B:	0.00
~~~	.~~~~~	.~~~~~~~	~~~~~	~~~~~~~	~~~~~~	~~~~~~	~~~~~
		EN RECALL A					N/O
IN	K		TODAY	N RECALL AS OF			N/C
	Tech(s):		TODAT				
Pts:		0.00 Lbr:		0.00 Other:	0.00	Total Line C:	0.00
~~~	~~~~~~						
D	DMV SI	-~~~~~~~ HEET	~~~~~	~~~~~~~	~~~~~~	~~~~~~	~~~~~
	DMV SI MV	IUC	DMV SH	 EET	~~~~~	~~~~~	N/C
DI	MV Tech(s):	IUC 29				T. (.11.: D	
DI	MV Tech(s):	IUC			0.00	Total Line D:	N/C 0.00
Pts: ~~~	MV Tech(s): FRONT	IUC 29 0.00 Lbr: WIPER REPI	~~~~~~ LACEMEN	0.00 Other: ~~~~~~ T (2X)	0.00	Total Line D:	0.00
Pts: ~~~	MV Tech(s):	IUC 29 0.00 Lbr: WIPER REPI	~~~~~~ LACEMEN FRONT	0.00 Other: ~~~~~~ T (2X) WIPER	0.00	Total Line D:	
Pts: ~~~	MV Tech(s): 	IUC 29 0.00 Lbr: WIPER REPI IUC	~~~~~~ LACEMEN FRONT	0.00 Other: ~~~~~~ T (2X)	0.00	Total Line D:	0.00
Pts: ~~~	MV Tech(s): FRONT IPER Tech(s):	IUC 29 0.00 Lbr: WIPER REPI IUC	LACEMEN FRONT REPLAC	0.00 Other: T (2X) WIPER EMENT (2X)		Total Line D:	0.00
Pts: ~~~	MV Tech(s): FRONT IPER Tech(s): SOA591	IUC 29 0.00 Lbr: 	LACEMEN FRONT REPLAC	0.00 Other: T (2X) WIPER EMENT (2X) 1 PB001826 26 WIPER B	6" BEAM	Total Line D:	0.00 N/C N/C
Pts: ~~~	MV Tech(s): FRONT IPER Tech(s):	IUC 29 0.00 Lbr: 	LACEMEN FRONT REPLAC	0.00 Other: T (2X) WIPER EMENT (2X)  1 PB001826 26 WIPER B 1 16" BEAM W	6" BEAM	Total Line D:	0.00 N/C
Pts:  ~~~ E**  W	MV Tech(s): FRONT IPER Tech(s): SOA591	IUC 29 0.00 Lbr: WIPER REPI IUC 29 B726	LACEMEN FRONT REPLAC	0.00 Other: T (2X) WIPER EMENT (2X)  1 PB001826 26 WIPER B 1 16" BEAM W (PAS	5" BEAM IPER BLADE	~~~~~~	0.00 N/C N/C N/C
Pts:  E**  W	MV Tech(s): FRONT IPER Tech(s): SOA591	IUC 29 0.00 Lbr: 	LACEMEN' FRONT V REPLAC	0.00 Other:  T (2X) WIPER EMENT (2X)  1 PB001826 26 WIPER B 1 16" BEAM W (PAS 0.00 Other:	5" BEAM IPER BLADE	Total Line D:	0.00 N/C N/C
Pts: E** W	MV Tech(s): FRONT IPER Tech(s): SOA591 SOA591	IUC 29 0.00 Lbr: WIPER REPI IUC 29 B726 B716 0.00 Lbr: 20 REPLACE	LACEMEN FRONT V REPLAC	0.00 Other:  T (2X) WIPER EMENT (2X)  1 PB001826 26 WIPER B 1 16" BEAM W (PAS 0.00 Other:	5" BEAM IPER BLADE	~~~~~~	0.00 N/C N/C N/C
Pts:  E**  W  Pts:  Stoil  F**	MV Tech(s): FRONT IPER Tech(s): SOA591 SOA591	IUC 29 0.00 Lbr: WIPER REPI IUC 29 B726 B716 0.00 Lbr:	ED FRONT	0.00 Other: T (2X) WIPER EMENT (2X)  1 PB001826 26 WIPER B 1 16" BEAM W (PAS 0.00 Other: WIPERS	5" BEAM IPER BLADE	~~~~~~	0.00 N/C N/C N/C
Pts:  E**  W  Pts:  Stoil  F**	MV Tech(s): FRONT /IPER Tech(s): SOA591 SOA591 ry: 92222 REAR V	IUC 29 0.00 Lbr: WIPER REPI IUC 29 B726 B716 0.00 Lbr: 20 REPLACE WIPER REPLACE	LACEMEN FRONT V REPLAC	0.00 Other:  T (2X) WIPER EMENT (2X)  1 PB001826 26 WIPER B 1 16" BEAM W (PAS 0.00 Other: WIPERS	5" BEAM IPER BLADE	~~~~~~	0.00 N/C N/C N/C 0.00
Pts:  E**  W  Pts:  Stoil  F**	MV Tech(s): FRONT IPER Tech(s): SOA591 SOA591 ry: 92222 REAR VIPERR Tech(s):	IUC 29 0.00 Lbr: WIPER REPI IUC 29 B726 B716 0.00 Lbr: 20 REPLACE WIPER REPLA IUC 29	ED FRONT	0.00 Other: T (2X) WIPER EMENT (2X)  1 PB001826 26 WIPER B 1 16" BEAM W (PAS 0.00 Other: WIPERS	6" BEAM IPER BLADE 0.00	~~~~~~	0.00 N/C N/C N/C 0.00
Pts:  E**  W  Pts:  Stoil  F**	MV Tech(s): FRONT /IPER Tech(s): SOA591 SOA591 ry: 92222 REAR V	IUC 29 0.00 Lbr: WIPER REPI IUC 29 B726 B716 0.00 Lbr: 20 REPLACE WIPER REPLA IUC 29	ED FRONT	0.00 Other:  T (2X) WIPER EMENT (2X)  1 PB001826 26 WIPER B 1 16" BEAM W (PAS 0.00 Other: WIPERS	BEAM IPER BLADE 0.00	~~~~~~	0.00 N/C N/C N/C 0.00

## Repair Order Detail - Customer Copy

RO Number: 461868 RO Status: CLOSED Customer: DAN PERKINS SUBARU NOEMAIL@EMAIL.COM Main: (203)882-5686 Phone(s): Contact: (203)882-5686 Cell: Vehicle: 4S3GTAC64K3738008 2019 IMPR SILVER AF72811 Mileage: 92,222 Payment type: CASH Waiter: No Promised time: 08:00 PM Service advisor: 290 Estimate: 0.00 Tag number: T008 Promised date: 11/26/2025 G** MOUNT AND BALANCE 4 TIRE MB4 IUC MOUNT AND BALANCE 4 N/C TIRE Tech(s): 29 28141SA556 4 2055516 ATREZZO SH408 N/C WWT 1 WHEEL WEIGHT N/C 0.00 Lbr: 0.00 Other: 0.00 Total Line G: Pts: 0.00 Story: 92222 100 MOUNTED 4 TIRES 4 WHEEL ALIGNMENT. INSPECT/ADJUST CASTER, CAMBER & TOE, INSPECT SUSPENSION & STEERING. TECH ROAD TESTED. 4 WHEEL ALIGNMENT. ALIGN IUC N/C INSPECT/ADJUST CASTER, CAMBER & TOE. **INSPECT SUSPENSION &** STEERING. TECH ROAD TESTED. Tech(s): 29 0.00 Lbr: 0.00 Other: 0.00 Total Line H: Pts: Story: 92222 100 PERFORM FULL FOUR WHEEL ALIGNMENT AND PERFORM QUALITY ROAD TEST TECH NOTED THE LOWER CONTROL ARM BUSHINGS NEED TO BE REPLACE 00 IUC REPLACE THE LOWER N/C CONTROL ARM BUSHINGS Tech(s): 29 20204FL01B 2 RUB BUSH ARM F R N/C 2 BUSHING TRANSVERSE 20204AG030 N/C LINK F 0.00 Lbr: 0.00 Other: 0.00 Total Line I: 0.00 Story: 92222 400 REPLACED CONTROL ARM BUSHINGS REAR BRAKE SERVICE: PADS & ROTORS IUC REAR BRAKE SERVICE: N/C RBJR PADS & ROTORS Tech(s): 29 26696FJ000 1 BRAKE PAD KIT REAR N/C 26700FJ000 2 BRAKE DISC R N/C 0.00 Lbr: 0.00 Other: Pts: 0.00 Total Line J: 0.00 Story: 92222 200 REPLACED REAR PADS AND ROTORS CUSTOMER STATES REPLACE DRIVE BELT

Page 2, Created: 12/01/2025 07:28:56 AM

## Repair Order Detail - Customer Copy

RO Number: 461868 RO Status: CLOSED

Customer: DAN PERKINS SUBARU NOEMAIL@EMAIL.COM Phone(s): Contact: (203)882-5686 Vehicle: 4S3GTAC64K3738008 Main: (203)882-5686 Cell: SILVER 2019 IMPR AF72811 Mileage: 92,222 Payment type: CASH Waiter: No Service advisor: 290 Promised time: 08:00 PM Estimate: Tag number: T008 Promised date: 11/26/2025 0.00 BELT IUC CUSTOMER STATES N/C REPLACE DRIVE BELT Tech(s): 29 23780ÁA08A 1 V BELT 0.00 Lbr: 0.00 Other: 0.00 Total Line K: N/C Pts: 0.00 Story: 92222 70 REPLACED DRIVE BELT L** SUBARU ENGINE AIR FILTER AIR IUC SUBARU ENGINE AIR N/C FILTER Tech(s): 29 N/C 0.00 Story: 92222 30 REPLACED AIR FILTER M** SUBARU CABIN AIR FILTER \$94.99 CABIN IUC SUBARU CABIN AIR FILTER \$94.99 N/C Tech(s): 29 72880FL00A 1 FILTER
Pts: 0.00 Lbr: 0.00 Other: 0.00 Total Line M: N/C 0.00 Story: 92222 30 REPLACED CABIN FILTER Customer Pay Labor 0.00 Parts 0.00 Lube 0.00 Sublet 0.00 Miscellaneous/Shop Charge 0.00 Deductible 0.00 **Total Charges** 0.00 Less Insurance/Adjustment 0.00 Sales Tax 0.00 Total 0.00