
Honda and Acura models with


ALPHA INFLATORS

The "Alpha" driver-front airbag inflators were the subject of the first Takata airbag inflator recalls starting in 2008, but some of the owners of these vehicles never completed the repairs. Now, because of the time that has passed, the inflators in these vehicles have shown a rupture rate as high as 50%, which can cause serious injuries or death to vehicle occupants.


Following are the vehicles and model years that are part of the "Alpha" inflator recall.



















For complete Honda and Acura recall information, please visit owners.honda.com/recalls or owners.acura.com/recalls