

March 7, 2017

 Ontario

Paint Protection Film

\$594.00

Guard your vehicle from weathering, UV radiation and road debris that can chip and scratch the finish with Genuine Toyota Paint Protection Film. This durable and nearly invisible thermoplastic urethane is designed to protect the hood and front fenders to maintain a like-new appearance to your Toyota. Backed by a 7 year limited warranty. At participating dealers only.

Body Side Moulding

\$278.00

Colour-matched body side mouldings help protect door panels from scratches, dents and chipping. Designed specifically to help preserve and enhance the vehicle's appearance. Unlike many aftermarket mouldings, genuine Toyota body side mouldings have undergone rigorous testing to ensure their resistance to temperature, weather, impact, stone chips, high pressure washing, wind noise and peeling. Body side mouldings also help maintain your vehicle's resale value.

Block Heater

\$246.00

Custom-designed system with 400 watts of heating power not only warms a vehicle up quicker but also reduces engine strain and wear. Heater saves fuel and battery power during startups as well. The strain relief electrical cord (available on selected models) reduces cord damage.

Cargo Mat

\$153.60

Designed to match the interior fabric of your Avalon and fit snugly inside the spacious trunk area, the cargo mat helps protect against premature wear and stains and features a stylish Avalon logo.

START+ Long Range Remote Engine Starter

\$786.20

Toyota START+ long range remote engine starter enables you to start your Toyota from 800 meters or 2,600 feet away (unobstructed). Toyota START+ activates your pre-set heating and air conditioning system, as well as your front and rear defoggers.

Non-Genuine remote engine starters and any damages or failures resulting from installation and use, are not covered by any Toyota warranty. Only the Genuine Toyota START+, is covered by Toyota warranty. All Non-Genuine remote engine starter installation is hostile and requires cutting, splicing and soldering of wires and/or require an additional immobilizer bypass device.

All features may not be applicable to all vehicle models.