

# Repair Order Detail - Customer Copy

RO Number: 460846

RO Status: CLOSED

Customer: DAN PERKINS SUBARU

Phone(s): Contact: (203)882-5686

Vehicle: JF2GTHSC4PH298836

Main: (203)882-5686

2023 CRTK

SILVER

[NOEMAIL@EMAIL.COM](mailto:NOEMAIL@EMAIL.COM)

Cell:

Mileage: 27,988

Service advisor: 290

Tag number: T9012

Payment type: CASH

Promised time: 08:00 PM

Promised date: 11/12/2025

Waiter: No

Estimate: 0.00

~~~~~  
A SAFETY CHECK & OIL AND FILTER CHANGE AND CHECK ALL FLUIDS  
SCLOF IUC SAFETY CHECK & OIL AND FILTER CHANGE AND CHECK ALL FLUIDS N/C

Tech(s): 29

15208AA21A

SOA635045

803916010

1 ELEM CP-OIL FLTR

6 OIL 0W20 SYNTH

1 GASKET

N/C

N/C

N/C

Pts: 0.00 Lbr: 0.00 Other: 0.00 Total Line A: 0.00

Story: 27988 150 PERFORM LUBE OIL AND FILTER CHANGE WITH GENUINE SUBARU PARTS AND FLUIDS

~~~~~  
B DMV SHEET  
DMV IUC PASS N/C

Tech(s): 29

Pts: 0.00 Lbr: 0.00 Other: 0.00 Total Line B: 0.00

~~~~~  
C NO OPEN RECALL AS OF TODAY  
NR IUC NO OPEN RECALL AS OF TODAY N/C

Tech(s): 29

Pts: 0.00 Lbr: 0.00 Other: 0.00 Total Line C: 0.00

~~~~~  
D CERTIFIED PRE-OWNED VEHICLE INSPECTION  
CPO IUC CERTIFIED PRE-OWNED VEHICLE INSPECTION N/C

Tech(s): 29

Pts: 0.00 Lbr: 0.00 Other: 0.00 Total Line D: 0.00

Story: 27988 50 performed cpo

~~~~~  
E\*\* FRONT WIPER REPLACEMENT (2X)  
WIPER IUC FRONT WIPER REPLACEMENT (2X) N/C

Tech(s): 29

SOA591B726

1 PB001826 26" BEAM

WIPER B

SOA591B716

1 16" BEAM WIPER BLADE

(PAS

N/C

N/C

Pts: 0.00 Lbr: 0.00 Other: 0.00 Total Line E: 0.00

Story: 27988 20 replaced front wipers

~~~~~  
F\*\* REAR WIPER REPLACEMENT  
WIPERR IUC REAR WIPER REPLACEMENT N/C

Tech(s): 29

# Repair Order Detail - Customer Copy

RO Number: 460846

RO Status: CLOSED

Customer: DAN PERKINS SUBARU

Phone(s): Contact: (203)882-5686

Vehicle: JF2GTHSC4PH298836

Main: (203)882-5686

2023 CRTK

SILVER

[NOEMAIL@EMAIL.COM](mailto:NOEMAIL@EMAIL.COM)

Cell:

Mileage: 27,988

Service advisor: 290

Tag number: T9012

Payment type: CASH

Promised time: 08:00 PM

Promised date: 11/12/2025

Waiter: No

Estimate: 0.00

~~~~~  
SOA591R612 1 12" REAR WIPER BLADE N/C  
Pts: 0.00 Lbr: 0.00 Other: 0.00 Total Line F: 0.00

Story: 27988 10 replaced rear wiper  
~~~~~

G\*\* SUBARU CABIN AIR FILTER \$94.99 N/C  
CABIN IUC SUBARU CABIN AIR  
FILTER \$94.99

Tech(s): 29

72880FL00A

1 FILTER

Pts: 0.00 Lbr: 0.00 Other: 0.00 Total Line G: 0.00

Story: 27988 30 replaced cabin filter  
~~~~~

H\*\* REAR BRAKE SERVICE: PADS & ROTORS N/C  
RBJR IUC REAR BRAKE SERVICE:  
PADS & ROTORS

Tech(s): 29

26696FJ000

1 BRAKE PAD KIT REAR

26700FJ000

2 BRAKE DISC R

Pts: 0.00 Lbr: 0.00 Other: 0.00 Total Line H: 0.00

Story: 27988 200 replaced rear rotors and pads  
~~~~~

I\*\* MOUNT AND BALANCE 4 TIRE N/C  
MB4 IUC MOUNT AND BALANCE 4  
TIRE

Tech(s): 29

28131ART17

4 225/60R17 ATTREZO

SH408

WWT

1 WHEEL WEIGHT

Pts: 0.00 Lbr: 0.00 Other: 0.00 Total Line I: 0.00

Story: 27988 100 mounted 4 tires  
~~~~~

J\*\* 4 WHEEL ALIGNMENT. INSPECT/ADJUST CASTER, CAMBER & TOE, INSPECT  
SUSPENSION & STEERING. TECH ROAD TESTED. N/C  
ALIGN IUC 4 WHEEL ALIGNMENT.  
INSPECT/ADJUST  
CASTER, CAMBER & TOE,  
INSPECT SUSPENSION &  
STEERING. TECH ROAD  
TESTED.

Tech(s): 29

Pts: 0.00 Lbr: 0.00 Other: 0.00 Total Line J: 0.00

Story: 27988 100 PERFORM FULL FOUR WHEEL ALIGNMENT AND PERFORM  
QUALITY ROAD TEST  
~~~~~

# Repair Order Detail - Customer Copy

RO Number: 460846

RO Status: CLOSED

Customer: DAN PERKINS SUBARU

[NOEMAIL@EMAIL.COM](mailto:NOEMAIL@EMAIL.COM)

Phone(s): Contact: (203)882-5686

Main: (203)882-5686

Cell:

Vehicle: JF2GTHSC4PH298836

2023 CRTK

SILVER

Mileage: 27,988

Payment type: CASH

Waiter: No

Service advisor: 290

Promised time: 08:00 PM

Estimate: 0.00

Tag number: T9012

Promised date: 11/12/2025

~~~~~  
K\*\* CUSTOMER STATES PERFORM FRONT AND REAR DIFFERENTIAL SERVICE.

DIFF

IUC

CUSTOMER STATES

N/C

PERFORM FRONT AND

REAR DIFFERENTIAL

SERVICE.

Tech(s): 29

SOA635301

3 HIGH PERF GEAR OIL

N/C

75W-90

803918060

4 GASKET 18X24X1.0

N/C

803926090

1 GASKET 26.3X32.3X1

N/C

Pts: 0.00 Lbr: 0.00 Other: 0.00 Total Line K: 0.00

Story: 27988 150 performed diff service

~~~~~  
Customer Pay

Labor

0.00

Parts

0.00

Lube

0.00

Sublet

0.00

Miscellaneous/Shop Charge

0.00

Deductible

0.00

Total Charges

0.00

Less Insurance/Adjustment

0.00

Sales Tax

0.00

Total

0.00