

2010 TOYOTA TACOMA

| TOYOTA ACCESSORIES | Part Number | Part Price | Installed Total | Price/Month 2 year | Price/Month 3 year | Price/Month 4 year | Price/Month 5 year | Price/Month 6 year |
|--|--------------------|-------------------|------------------------|-----------------------|-----------------------|-----------------------|-----------------------|-----------------------|
| All Weather Floor Mats | N/A | | | | | | | |
| Alloy Wheel | | | | | | | | |
| Baja 16" (x4 @ \$260 ea.) | PT758-35061 | \$1,040 | \$1,105 | 50.48 | 35.13 | 27.49 | 22.93 | 19.91 |
| *Will need to get wheel sensors if not using originals | | | | | | | | |
| Ashtray Kit | | | | | | | | |
| Retainer Ring | 74128-02020 | \$6 | | | | | | |
| Cup | 74102-02140 | \$22 | | | | | | |
| Total | | \$28 | \$28 | 1.28 | 0.89 | 0.70 | 0.58 | 0.50 |
| Auto-Dimming Mirror | | | | | | | | |
| Xtra/D-Cab | PT374-35053 | \$290 | \$521 | 23.80 | 16.56 | 12.96 | 10.81 | 9.39 |
| Std Cab | PT374-35052 | " | " | | | | | |
| Bed Extender | PT329-35050 | \$280 | \$319 | 14.55 | 10.13 | 7.92 | 6.61 | 5.74 |
| Bed Mats | | | | | | | | |
| Long Bed | PT580-35050-LB | \$120 | \$120 | 5.48 | 3.81 | 2.99 | 2.49 | 2.16 |
| Short Bed | PT580-35050-SB | " | " | | | | | |
| Bed Nets | | | | | | | | |
| Short Bed | PT347-35051 | \$115 | \$115 | 5.25 | 3.66 | 2.86 | 2.39 | 2.07 |
| Long Bed | PT347-35052 | " | " | | | | | |
| Bed Rugs | | | | | | | | |
| Long Bed | PTS12-35050 | \$380 | \$419 | 19.12 | 13.30 | 10.41 | 8.68 | 7.54 |
| Short Bed | PTS12-35051 | " | " | | | | | |
| Cargo Nets | PT347-35050 | \$35 | \$35 | 1.60 | 1.11 | 0.87 | 0.73 | 0.63 |

Prices are subject to change
Interest rate is shown at 9% APR

2010 TOYOTA TACOMA

| TOYOTA ACCESSORIES | Part Number | Part Price | Installed Total | Price/Month 2 year | Price/Month 3 year | Price/Month 4 year | Price/Month 5 year | Price/Month 6 year |
|--|--------------------|-------------------|------------------------|-----------------------|-----------------------|-----------------------|-----------------------|-----------------------|
| Carpet Floor Mats | | | | | | | | |
| 2pc Fronts - Lt. Charcoal | PT206-35080-11 | \$89 | \$89 | 4.07 | 2.83 | 2.21 | 1.85 | 1.60 |
| 2pc Fronts - Oak | PT206-35080-14 | " | " | | | | | |
| 4pc Access Cab - Lt. Charcoal | PT206-35081-11 | \$135 | \$135 | 6.17 | 4.29 | 3.36 | 2.80 | 2.43 |
| 4pc Access Cab - Oak | PT206-35081-14 | " | " | | | | | |
| 4pc Access Cab - TRD Off-Road | PT206-35085-11 | \$140 | \$140 | 6.40 | 4.45 | 3.48 | 2.91 | 2.52 |
| 4pc D-Cab - Oak | PT206-35082-14 | \$135 | \$135 | 6.17 | 4.29 | 3.36 | 2.80 | 2.43 |
| 4pc D-Cab - Lt. Charcoal | PT206-35082-11 | " | " | | | | | |
| 4pc D-Cab - TRD Off-Road | PT206-35086-11 | \$140 | \$140 | 6.40 | 4.45 | 3.48 | 2.91 | 2.52 |
| Door Sill Protector | | | | | | | | |
| Std Cab | PT747-35050 | \$30 | \$69 | 3.13 | 2.18 | 1.70 | 1.42 | 1.23 |
| Xtra Cab | PT747-35051 | " | " | | | | | |
| Double Cab | PT747-35052 | \$35 | \$74 | 3.38 | 2.35 | 1.84 | 1.54 | 1.33 |
| Emergency Assistance Kit | | | | | | | | |
| | PT420-00045 | \$92 | \$92 | 4.20 | 2.92 | 2.29 | 1.91 | 1.66 |
| Exhaust Tip (not for X-Runner) | | | | | | | | |
| | PT18A-35090 | \$60 | \$99 | 4.50 | 3.13 | 2.45 | 2.04 | 1.77 |
| First Aid Kit | | | | | | | | |
| | PT420-03023 | \$33 | \$33 | 1.51 | 1.05 | 0.82 | 0.68 | 0.59 |
| Front Skid Plate (pre-runr & 4x4 only) | | | | | | | | |
| | PT212-35075 | \$220 | \$297 | 13.57 | 9.44 | 7.39 | 6.16 | 5.35 |
| Hood Protector | | | | | | | | |
| | PT427-35060 | \$110 | \$149 | 6.78 | 4.72 | 3.69 | 3.08 | 2.68 |
| Interface Kit for iPod* | | | | | | | | |
| | PT545-00082 | \$255 | \$332 | 15.17 | 10.55 | 8.26 | 6.89 | 5.98 |
| *Doesn't work w/ Satellite Radio installed, JBL, or Nav | | | | | | | | |
| *Audio unit must be base grade Sat. ready | | | | | | | | |
| Roof Rack & Attachements* | | | | | | | | |
| D-Cab Stowaway Rack | PT278-35050 | \$300 | \$377 | 17.22 | 11.98 | 9.38 | 7.82 | 6.79 |
| Yakima Big Powderhound | 36745-03072 | \$155 | \$194 | 8.86 | 6.17 | 4.83 | 4.03 | 3.50 |
| *Adapter Kit | PT278-35061 | \$90 | | | | | | |
| Bike Rack (*need adapt kit) | PT278-89063 | \$195 | | | | | | |
| Total (per bike) | | \$285 | \$324 | 14.78 | 10.28 | 8.05 | 6.71 | 5.83 |

Prices are subject to change
Interest rate is shown at 9% APR

2010 TOYOTA TACOMA

| TOYOTA ACCESSORIES | Part Number | Part Price | Installed Total | Price/Month 2 year | Price/Month 3 year | Price/Month 4 year | Price/Month 5 year | Price/Month 6 year |
|--|--------------------|-------------------|------------------------|-------------------------------|-------------------------------|-------------------------------|-------------------------------|-------------------------------|
| Running Boards | | | | | | | | |
| Double Cab | PT212-35055 | \$385 | \$462 | 21.10 | 14.69 | 11.49 | 9.59 | 8.33 |
| Xtra Cab | PT212-35053 | \$345 | \$422 | 19.28 | 13.42 | 10.50 | 8.76 | 7.60 |
| Satellite Radio | | | | | | | | |
| XM Receiver | 86180-0W032 | \$250 | | | | | | |
| XM Fit Kit | PT546-35090 | \$150 | | | | | | |
| Total | | \$400 | \$554 | 25.31 | 17.61 | 13.78 | 11.50 | 9.98 |
| Sirius Receiver | PT545-35090 | \$250 | | | | | | |
| Sirius Fit Kit | PT545-00080 | \$150 | | | | | | |
| Total | | \$400 | \$554 | 25.31 | 17.61 | 13.78 | 11.50 | 9.98 |
| Blu logic hands free comm.* | | | | | | | | |
| | PT923-00098 | \$230 | | | | | | |
| Small Switch service part | PT923-00090-SW | \$48 | | | | | | |
| Total | | \$278 | \$355 | 16.22 | 11.29 | 8.83 | 7.37 | 6.40 |
| *Doesn't work w/ JBL or Nav. | | | | | | | | |
| *Not available For TRD off-road package | | | | | | | | |
| Seat Covers | | | | | | | | |
| TRD Off-Road Bucket Seats - Graphite | PT218-35052-01 | \$210 | \$249 | 11.35 | 7.90 | 6.18 | 5.16 | 4.48 |
| SR5 / Base Bucket Seat - Graphite | PT218-35059-01 | " | " | | | | | |
| SR5 / Base Bucket Seat - Taupe | PT218-35059-04 | " | " | | | | | |
| Shift Knobs by OBX | | | | | | | | |
| Red | PTS22-00030 | \$35 | \$74 | 3.36 | 2.34 | 1.83 | 1.53 | 1.32 |
| Blue | PTS22-00031 | " | " | | | | | |
| Chrome | PTS22-00032 | " | " | | | | | |
| Titanium | PTS22-00033 | " | " | | | | | |
| Spare Tire Lock | | | | | | | | |
| | PT276-35060 | \$49 | \$49 | 2.24 | 1.56 | 1.22 | 1.02 | 0.88 |
| Tail Gate Lock *(Pop-n-lock - Titan) | | | | | | | | |
| 2005-2008 | PL5200 | \$75 | \$144 | 6.58 | 4.58 | 3.58 | 2.99 | 2.59 |
| (Back-up camera version) 2009-2010 | PL5300 | NOT | | | | | | |

Prices are subject to change
Interest rate is shown at 9% APR

2010 TOYOTA TACOMA

| TOYOTA ACCESSORIES | Part Number | Part Price | Installed Total | Price/Month 2 year | Price/Month 3 year | Price/Month 4 year | Price/Month 5 year | Price/Month 6 year |
|--|--------------------|-------------------|------------------------|-----------------------|-----------------------|-----------------------|-----------------------|-----------------------|
| Towing Hitch & Accessories | | | | | | | | |
| Hitch Class I, II, & III | PT791-04050 | \$350 | | | | | | |
| Wiring Harness | 08921-04960 | \$110 | | | | | | |
| Total | | \$460 | \$614 | 28.05 | 19.52 | 15.28 | 12.74 | 11.06 |
| 7 To 4 Pin Adapter | PT791-89040 | \$11 | \$11 | 0.50 | 0.35 | 0.27 | 0.23 | 0.20 |
| Ball Mount | PT228-00950 | \$60 | \$60 | 2.74 | 1.91 | 1.49 | 1.25 | 1.08 |
| Ball Mount | PT214-60034 | " | " | | | | | |
| 2 5/16" Ball | PT791-00850 | \$38 | \$38 | 1.74 | 1.21 | 0.95 | 0.79 | 0.68 |
| 2" Ball | PT791-00844 | \$25 | \$25 | 1.14 | 0.79 | 0.62 | 0.52 | 0.45 |
| TRD | | | | | | | | |
| (V6 D-Cab/V6 Xtra Cab StdBox) Exhaust Single Outlet | PT910-89061 | \$505 | \$582 | 26.59 | 18.50 | 14.48 | 12.08 | 10.49 |
| (V6 D-Cab LongBox) Exhaust Single Outlet | PT910-89060 | \$525 | \$602 | 27.50 | 19.14 | 14.98 | 12.49 | 10.85 |
| Flo-Master Dual Exhaust* | | | | | | | | |
| 05-10 Tacoma 4.0L 2 & 4wd | 17432 | \$425 | \$502 | 22.93 | 15.96 | 12.49 | 10.42 | 9.05 |
| *Not for StdCab & X-Runner | | | | | | | | |
| 16" x 8" 5-Spoke Wheel (x4 @ \$265 ea.) | PTR20-34070 | \$1,060 | \$1,125 | 51.39 | 35.76 | 27.99 | 23.34 | 20.27 |
| 16" x 7.5" Bronze TRD Wheel (x4 @ \$225 ea.) | PTR18-35090-BR | \$900 | \$965 | 44.08 | 30.68 | 24.01 | 20.02 | 17.39 |
| Quick Shifter | PTR04-35052 | \$350 | | | | | | |
| Quick Shifter Knob | PTR26-35060 | \$47 | | | | | | |
| Total | | \$397 | \$474 | 21.65 | 15.07 | 11.79 | 9.84 | 8.54 |
| Air Filter V6 | PTR05-35060 | \$85 | \$85 | 3.88 | 2.70 | 2.11 | 1.76 | 1.53 |
| (05-09 Only) Cold Air Intake V6 | PTR03-35090 | \$475 | \$591 | 26.97 | 18.77 | 14.69 | 12.25 | 10.64 |
| Oil Filter | PTR43-00080 | \$13 | \$13 | 0.59 | 0.41 | 0.32 | 0.27 | 0.23 |
| (after retail sale of vehicle) Supercharger for 4.0L | PTR29-35090 | \$4,150 | | | | | | |
| (4.0L) Fit kit | PTR29-35100 | \$380 | | | | | | |
| Total | | \$4,530 | \$4,992 | 228.03 | 158.70 | 124.20 | 103.58 | 89.96 |
| Truck Bed Accessories | | | | | | | | |
| Tool Box - Large | PT767-35050 | \$600 | \$639 | 29.17 | 20.30 | 15.89 | 13.25 | 11.51 |
| Cargo Divider | PT767-35051 | \$280 | \$319 | 14.57 | 10.14 | 7.94 | 6.62 | 5.75 |
| Side Tool Box - Small | PT767-35052 | \$295 | \$334 | 15.26 | 10.62 | 8.31 | 6.93 | 6.02 |
| (N/A re-tooling as of Aug '09) Side Rail Bed Cleat (One) | PT785-35050-S1 | | | | | | | |
| Mini Tie-Down (1 pair) | PT278-35075 | \$45 | \$45 | 2.06 | 1.43 | 1.12 | 0.93 | 0.81 |

Prices are subject to change
Interest rate is shown at 9% APR

2010 TOYOTA TACOMA

| TOYOTA ACCESSORIES | Part Number | Part Price | Installed Total | Price/Month 2 year | Price/Month 3 year | Price/Month 4 year | Price/Month 5 year | Price/Month 6 year |
|---|--------------------|-------------------|----------------------------|-----------------------|-----------------------|-----------------------|-----------------------|-----------------------|
| (Yakima) Fork Mount Bike Attachment (One Per Bike) | PTS08-34070 | \$110 | \$149 | 6.81 | 4.74 | 3.71 | 3.09 | 2.68 |
| Cargo Cross Bars | PT785-35053 | \$130 | \$169 | 7.72 | 5.37 | 4.20 | 3.51 | 3.05 |
| D-Rings (1 pair) | PT785-35054 | \$30 | \$69 | 3.15 | 2.19 | 1.72 | 1.43 | 1.24 |
| Tube Steps (Silver w/ black pads) | | | | | | | | |
| Std Cab | PTS09-35060 | \$355 | \$432 | 19.73 | 13.73 | 10.75 | 8.96 | 7.78 |
| Xtra Cab | PTS09-35061 | \$415 | \$492 | 22.47 | 15.64 | 12.24 | 10.21 | 8.87 |
| D-Cab Long Box | PTS09-35062 | \$435 | \$512 | 23.39 | 16.28 | 12.74 | 10.62 | 9.23 |
| D-Cab Short Box | PTS09-35063 | \$415 | \$492 | 22.47 | 15.64 | 12.24 | 10.21 | 8.87 |
| VIP (must have remote keyless entry) | | | | | | | | |
| *RS3200 Plus | PT398-35090 | \$360 | \$476 | 21.72 | 15.12 | 11.83 | 9.87 | 8.57 |
| <i>*Doesn't work w/ Dcab w/ side curtain airbag & theft sytem</i> | | | | | | | | |
| Wheel Locks | | | | | | | | |
| 16" & 18" Factory Wheel | 00276-00900 | \$50 | \$89 | 4.04 | 2.81 | 2.20 | 1.84 | 1.59 |
| 16" Accessory Wheel & 17" Factory Alloy | 00276-00901 | " | " | | | | | |
| Factory Fog Lights | | | | | | | | |
| RH Lamp | 81210-AA030 | \$200 | | | | | | |
| LH Lamp | 81210-AA030 | \$200 | | | | | | |
| RH Fog Lamp Connector | 90080-11659 | \$8 | | | | | | |
| LH Fog Lamp Connector | 90080-11659 | \$8 | | | | | | |
| Fog Lamp Switch Connector | 90980-11090 | \$5 | | | | | | |
| Wires for Connector (x4 @ \$6.00 ea.) | 82998-24150 | \$24 | | | | | | |
| Fog Lamp Switch - lighted | 84160-04010 | \$54 | | | | | | |
| Relay | 90080-87026 | \$66 | | | | | | |
| (Titan) PIAA Wire Harness | 34085 | \$55 | | | | | | |
| Total | | \$620 | \$813 | 37.12 | 25.83 | 20.22 | 16.86 | 14.64 |

Prices are subject to change
Interest rate is shown at 9% APR

2010 TOYOTA TACOMA

| TOYOTA ACCESSORIES | Part Number | Part Price | Installed Total | Price/Month 2 year | Price/Month 3 year | Price/Month 4 year | Price/Month 5 year | Price/Month 6 year |
|--|--------------------|-------------------|------------------------|-----------------------|-----------------------|-----------------------|-----------------------|-----------------------|
| TRD Sport Hood | | | | | | | | |
| Hood | 53301-04170 | \$430 | | | | | | |
| Bulge Kit | 76181-35050-xx | \$121 | | | | | | |
| Rivits (x10 @ \$1 ea.) | 90269-04054 | \$10 | | | | | | |
| Plate | 76192-35020 | \$21 | | | | | | |
| Guide | 76182-35060 | \$20 | | | | | | |
| Nuts (x10 @ \$1 ea.) | 90080-17210 | \$10 | | | | | | |
| Label Emissions | depends on year | \$3 | | | | | | |
| Label Vacumm | depends on year | \$4 | | | | | | |
| Paint | Autobody Shop | \$350 | | | | | | |
| Total | | \$969 | \$1,085 | 49.54 | 34.48 | 26.98 | 22.50 | 19.54 |
| AFTERMARKET ACCESSORIES | | | | | | | | |
| ARB Bumper | | | | | | | | |
| Warn 8000 Lb Winch | W26502 | \$950 | | | | | | |
| Skyjacker Leveling Kit | TT20MS | \$250 | | | | | | |
| Alignment | | | | | | | | |
| Freight | | \$150 | | | | | | |
| Total | | \$2,650 | \$3,343 | 152.71 | 106.27 | 83.17 | 69.37 | 60.24 |
| Billet Grill Set (T-Rex)(Amer. Trk) | | | | | | | | |
| Grill (cut-out), Side Vents, Bumper | 20895C | \$400 | \$477 | 21.79 | 15.16 | 11.87 | 9.90 | 8.60 |
| (Sport Hood Option) Hood Piece | 20897 | \$75 | | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 |
| Total for Sport Hood option | | \$475 | \$591 | 26.97 | 18.77 | 14.69 | 12.25 | 10.64 |
| Mesh Black Grill 3pc Combo (t-rex)(amer. trk) | | | | | | | | |
| Grill (cut-out), Side Vents, Bumper | 6718951C | \$740 | \$817 | 37.32 | 25.97 | 20.33 | 16.95 | 14.72 |
| (Sport Hood Option) Hood Piece | 51897 | \$110 | | | | | | |
| Total for Sport Hood option | | \$850 | \$966 | 44.13 | 30.71 | 24.03 | 20.04 | 17.41 |
| Mesh Grill 3pc Combo (T-Rex)(Amer. Trk) | | | | | | | | |
| Grill (cut-out), Side Vents, Bumper | 54895C | \$595 | \$672 | 30.70 | 21.36 | 16.72 | 13.94 | 12.11 |
| (Sport Hood Option) Hood Piece | 54897 | \$110 | | | | | | |
| Total for Sport Hood option | | \$705 | \$821 | 37.50 | 26.10 | 20.43 | 17.04 | 14.79 |

Prices are subject to change
Interest rate is shown at 9% APR

2010 TOYOTA TACOMA

| TOYOTA ACCESSORIES | Part Number | Part Price | Installed Total | Price/Month 2 year | Price/Month 3 year | Price/Month 4 year | Price/Month 5 year | Price/Month 6 year |
|---|--------------------------------------|-------------------|------------------------|-----------------------|-----------------------|-----------------------|-----------------------|-----------------------|
| Block Heater | | | | | | | | |
| 4cyl | 00213-02141 | \$39 | \$155 | 7.06 | 4.91 | 3.84 | 3.21 | 2.78 |
| V6 | 00213-00900 | \$54 | \$170 | 7.74 | 5.39 | 4.22 | 3.52 | 3.05 |
| Bugshield (Focus) | | | | | | | | |
| | 71621-99353 | \$105 | \$144 | 6.56 | 4.56 | 3.57 | 2.98 | 2.59 |
| Class III Hitch (Curt) | | | | | | | | |
| | 13323 | \$232 | | | | | | |
| T-one Wiring Harness (Drawtite) | | | | | | | | |
| | 18393 | \$60 | | | | | | |
| | Stinger (Drawtite) | 40342 | \$22 | | | | | |
| | 2" Chrome Ball (Drawtite) | 5082 | \$11 | | | | | |
| | Pin for Stinger (Drawtite) | 4667 | \$6 | | | | | |
| | Total | \$331 | \$485 | 22.15 | 15.42 | 12.07 | 10.06 | 8.74 |
| 2pc std cab Vent Visors | | | | | | | | |
| | 25478-07353 | \$60 | \$99 | 4.50 | 3.13 | 2.45 | 2.04 | 1.77 |
| 2pc X-Cab Vent Visors | | | | | | | | |
| | 25478-07354 | \$60 | " | | | | | |
| 4pc Double Cab Vent Visors | | | | | | | | |
| | 25478-07352 | \$75 | \$114 | 5.21 | 3.62 | 2.84 | 2.37 | 2.05 |
| Grill Guard - Black (Aries) | | | | | | | | |
| | 2054 | \$535 | \$612 | 27.96 | 19.46 | 15.23 | 12.70 | 11.03 |
| DVD Headrests (Aspen) | | | | | | | | |
| Rosen | Sublet | | \$1,800 | 82.22 | 57.22 | 44.78 | 37.35 | 32.44 |
| Drop Down DVD 10" (Aspen) | | | | | | | | |
| | Sublet | | \$1,000 | 45.68 | 31.79 | 24.88 | 20.75 | 18.02 |
| Firestone RideRite Air Bags (Titan) | | | | | | | | |
| | 2407 | \$340 | \$494 | 22.57 | 15.70 | 12.29 | 10.25 | 8.90 |
| | (Dual Guage) Air Command Compressor | 2178 | \$833 | 38.05 | 26.48 | 20.73 | 17.28 | 15.01 |
| | Total (Bags & Compressor) | \$865 | \$1,327 | 60.62 | 42.19 | 33.02 | 27.54 | 23.91 |
| 3" Dominator II Nerf w/ hoop bar (Titan) | | | | | | | | |
| (Black) Dbl Cab | D24429B | \$523 | \$600 | 27.41 | 19.07 | 14.93 | 12.45 | 10.81 |
| Roll-up Tonneau Cover Lo-pro(Truxedo) | | | | | | | | |
| | Standard Cab/Xtra Cab Bed | 556801 | \$475 | \$552 | 25.22 | 17.55 | 13.73 | 11.45 |
| | Double Cab Short Bed | 555801 | " | " | | | | |
| | Double Cab Long Bed | 556801 | " | " | | | | |
| Seat Heaters (Katzkin) | | | | | | | | |
| | HEATER1 | \$165 ea. | \$281 ea. | | | | | |

Prices are subject to change
Interest rate is shown at 9% APR

2010 TOYOTA TACOMA

| TOYOTA ACCESSORIES | Part Number | Part Price | Installed Total | Price/Month 2 year | Price/Month 3 year | Price/Month 4 year | Price/Month 5 year | Price/Month 6 year |
|--|--------------------|-------------------|------------------------|-----------------------|-----------------------|-----------------------|-----------------------|-----------------------|
| <i>Tool Box (UWS - Titan)</i> | TBS-63A | \$365 | \$404 | 18.45 | 12.84 | 10.05 | 8.38 | 7.28 |
| <i>Tonneau Cover Black Plastic (Undercover)</i> | | | | | | | | |
| DCab Short Box (5' Box) | 4050 | \$820 | \$897 | 40.97 | 28.52 | 22.32 | 18.61 | 16.16 |
| Reg Cab/Xtra Cab/DCab Long Box (6' Box) | 4060 | " | " | | | | | |

Prices are subject to change
Interest rate is shown at 9% APR