

This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 6/16/18 at 10:03:01 AM (CDT). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.

CARFAX Ownership History The number of owners is estimated	🚨 Owner 1	Cwner 2
Year purchased	2013	2016
Type of owner	Commercial	Personal
Estimated length of ownership	3 yrs. 2 mo.	1 yr. 10 mo.
Owned in the following states/provinces	Florida, Michigan	Michigan
Estimated miles driven per year	8,225/yr	6,233/yr
Last reported odometer reading	26,367	38,094

CARFAX Title History CARFAX guarantees the information in this section	A Owner 1	Sowner 2
Salvage Junk Rebuilt Fire Flood Hail Lemon	Guaranteed No Problem	Guaranteed No Problem
Not Actual Mileage Exceeds Mechanical Limits	Guaranteed No Problem	Guaranteed No Problem





No structural damage reported to CARFAX.		
Airbag Deployment No airbag deployment reported to CARFAX.	No Issues Reported	No Issues Reported
Odometer Check No indication of an odometer rollback.	No Issues Indicated	No Issues Indicated
Accident / Damage No accidents or damage reported to CARFAX.	No Issues Reported	No Issues Reported
Manufacturer Recall No open recalls reported to CARFAX. Check for open recalls on GM vehicles at recalls.gm.com.	No Recalls Reported	No Recalls Reported
Basic Warranty Original warranty estimated to have expired.	Warranty Expired	Warranty Expired

ARF	Ax Deta	ailed Histo	ory		Glo
Owner 1		Date:	Mileage:	Source:	Comments:
urchased: ype: /here: st. miles/year: st. length wned:	2013 Commercial Florida, Michigan 8,225/yr 4/8/13 - 6/30/16	Original Equipment		OnStar	Vehicle equipped with OnStar Get 3 free months of premium OnStar with Automatic Crash Response, Roadside Assistance and Remote Door Unlock by pressing the blue OnStar button Learn more
ow mileage! nis owner drove	(3 yrs. 2 mo.)	03/19/2013	3	Jerry Hamm Chevrolet Jacksonville, FL 904-398-3036 jerryhamm.com	Pre-delivery inspection completed
dustry average 15,000 miles er year.	CAR	04/08/2013	10	Florida Motor Vehicle Dept. Jacksonville, FL Title #0111490917	Vehicle purchase reported Title issued or updated Registration issued or renewed First owner reported Loan or lien reported Titled or registered as commercial vehicle Vehicle color noted as Silver
		04/24/2013		Fleet Management Co. Farmington, MI	Vehicle purchased by fleet lease company
		02/02/2014	7,272	Service Facility Tampa, FL	Tires serviced Oil and filter changed
		02/14/2014		Florida Motor Vehicle Dept. Tampa, FL Title #0111490917	Registration issued or renewed Loan or lien reported Registration updated when owner moved the vehicle to a new location Vehicle color noted as Silver
		10/03/2014	15,481	Service Facility Akron, OH	Tires serviced Oil and filter changed
		02/09/2015		Florida Motor Vehicle Dept. Tampa, FL Title #0111490917	Registration issued or renewed Loan or lien reported Vehicle color noted as Silver
		08/08/2015	20,767	Service Facility Philadelphia, PA	Brakes serviced Tires serviced Oil and filter changed
		10/07/2015	22,000	Service Facility Saint Louis, MO	Vehicle serviced Engine serviced
		10/13/2015	22,405	Integrity Chevrolet Chattanooga, TN 423-535-9455 integritychevrolet.c om/	Vehicle serviced

01/23/2016	24,169	Service Facility Chattanooga, TN	Vehicle serviced Charging system serviced
01/28/2016	24,174	Mountain View Chevrolet Chattanooga, TN 423-888-0009 mtnviewchevy.com	Maintenance inspection completed Battery replaced
03/25/2016		Service Facility Saint Louis, MO	Vehicle serviced Tires serviced A/C system serviced
03/28/2016	24,679	Mountain View Chevrolet Chattanooga, TN 423-888-0009 mtnviewchevy.com	Tires serviced Maintenance inspection completed Two tires mounted
06/20/2016	26,020	Valvoline Instant Oil Change Lexington, KY 859-543-1154 vioc.com	Oil and filter changed
06/21/2016	26,367	Feldman Chevrolet of Livonia Livonia, MI 734-425-6500 tennysonchevy.com	Maintenance inspection completed Camshaft position sensor replaced Exhaust repaired
06/29/2016		Michigan Motor Vehicle Dept. Farmington, MI	Registration issued or renewed

\cap	NA/	/In	٩r	2
\smile	ww		CI	-

Purchased: 2016
Type: Personal
Where: Michigan
Est. miles/year: 6,233/yr
Est. length owned: 6/30/16 -

2016 Personal Michigan 6,233/yr 6/30/16 -5/17/18 (1 yr. 10 mo.)

Low mileage! This owner drove

less than the industry average of 15,000 miles per year.



Date:	Mileage:	Source:	Comments:
06/30/2016	26,378	Michigan Motor Vehicle Farmington, M Title #605E181	11
03/31/2017	29,647	Valvoline Insta Change Farmington, M 248-474-5990 vioc.com	Oil and filter changed Front wiper blades/refills replaced
05/10/2017		Michigan Motor Vehicle Farmington, M	
05/24/2017		Michigan Motor Vehicle Sparks Glenco	
05/17/2018	38,094	Auto Auction Michigan	Vehicle sold at auction Millions of used vehicles are bought and sold at auction every year.
05/17/2018		Michigan Motor Vehicle Sparks Glenco	'
05/22/2018		Fleet Manager Co. Farmington, M	
06/16/2018		myCARFAX	Manufacturer Recommended Maintenance Schedules
			Get this vehicle's maintenance schedule, service history and recall alerts at myCARFAX.com.



Print this CARFAX Report and take it to your pre-purchase inspection

Have Questions? Please visit our Help Center at www.carfax.com.



View Full Glossary

Commercial

Vehicle was registered for business purposes.

First Owner

When the first owner(s) obtains a title from a Department of Motor Vehicles as proof of ownership.

New Owner Reported

When a vehicle is sold to a new owner, the Title must be transferred to the new owner(s) at a Department of Motor Vehicles.

Ownership History

CARFAX defines an owner as an individual or business that possesses and uses a vehicle. Not all title transactions represent changes in ownership. To provide estimated number of owners, CARFAX proprietary technology analyzes all the events in a vehicle history. Estimated ownership is available for vehicles manufactured after 1991 and titled solely in the US including Puerto Rico. Dealers sometimes opt to take ownership of a vehicle and are required to in the following states: Maine, Massachusetts, New Jersey, Ohio, Oklahoma, Pennsylvania and South Dakota. Please consider this as you review a vehicle's estimated ownership history.

Title Issued

A state issues a title to provide a vehicle owner with proof of ownership. Each title has a unique number. Each title or registration record on a CARFAX report does not necessarily indicate a change in ownership. In Canada, a registration and bill of sale are used as proof of ownership.







CARFAX DEPENDS ON ITS SOURCES FOR THE ACCURACY AND RELIABILITY OF ITS INFORMATION. THEREFORE, NO RESPONSIBILITY IS ASSUMED BY CARFAX OR ITS AGENTS FOR ERRORS OR OMISSIONS IN THIS REPORT. CARFAX FURTHER EXPRESSLY DISCLAIMS ALL WARRANTIES, EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE. CARFAX®

SYSTEMATIC RETRIEVAL OF THE CONTENT OR OTHER DATA FROM THIS SITE TO CREATE OR COMPILE, DIRECTLY OR INDIRECTLY, IN WHOLE OR IN PART, A COLLECTION, COMPILATION, DATABASE OR DIRECTORY WITHOUT THE EXPRESS WRITTEN PERMISSION OF CARFAX IS STRICTLY PROHIBITED. THE CARFAX VEHICLE HISTORY REPORT IS SUBJECT TO THE CARFAX.COM TERMS OF USE.

© 2018 CARFAX, Inc., a unit of IHS Markit. All rights reserved.

Covered by United States Patent Nos. 7,113,853; 7,778,841; 7,596,512, 8,600,823; 8,595,079; 8,606,648; 7,505,838. 6/16/18 10:03:01 AM (CDT)

2013 CHEVROLET MALIBU LS

VIN: 1G11A5SA1DF246460 **Body Style: SEDAN 4 DR**

Engine Size: 2.5L I4 F DOHC 16V **Drivetrain: FRONT WHEEL DRIVE**

Original Manufacturer's Warranty:

Basic Warranty Expired

Please confirm remaining factory warranty and extended warranty options with your dealer!

The original manufacturer's warranty includes:

36 months or 36,000 miles

Information excerpted from the CARFAX Vehicle History Report and/or Safety & Reliability Ratings; see full reports for additional information, glossary of terms, source attributions, disclaimers & limitations. Go to carfax.com for complete Buyback Guarantee terms and conditions.

OWNERSHIP HISTORY: **Number of Owners:** Last owned in the following Michigan state/province: 7,455 Annual average mileage: LOW MILEAGE

STATE DMV-REPORTED TITLE PROBLEMS:

None of these major title problems were reported by a state Department of Motor Vehicles:



Salvage, Junk, Rebuilt, Fire,	Guaranteed
Flood, Hail, Lemon	No Problem
Not Actual Mileage, Exceeds	Guaranteed
Mechanical Limits	No Problem

ACCIDENTS AND OTHER ISSUES:

No issues reported to CARFAX on the following:

Total Loss	No Issues Reported
Structural Damage	No Issues Reported
Airbag Deployment	No Issues Reported
Odometer Rollback	No Issues Reported
Other Accidents / Damage	No Issues Reported

SHOW ME THE CARFAX

© 2018 CARFAX, Inc., a unit of IHS Markit. All rights reserved. Covered by United States Patent Nos. 7,113,853; 7,778,841; 7,596,512, 8,600,823; 8,595,079; 8,606,648; 7,505,838.6/16/18 10:03:01 AM (CDT)

^{*}Below industry annual average of 15,000 miles

Options



CARFAX* SmartBuyer Checklist

Vehicle Information:

2013 CHEVROLET MALIBU LS VIN: 1G11A5SA1DF246460 SEDAN 4 DR 2.5L I4 F DOHC 16V GASOLINE FRONT WHEEL DRIVE Standard Equipment | Safety

CARFAX Vehicle History Report Summary:



No accidents reported to CARFAX



No other damage reported to CARFAX



2 Previous owners



13 Service history records



Types of owners: Commercial, Personal



38,094 Last reported odometer reading



PRINT AND TAKE THIS CHECKLIST WITH YOU

This checklist utilizes information from your CARFAX report to help you make an informed used car purchase.

General Questions

Is the car still under manufacturer warranty or is a warranty available at the time of purchase?

Test Drive and Visual Inspection

Turn on the ignition without starting the car. Do all the warning lights and gauges work?

Ensure the airbag light appears momentarily and goes out upon starting the vehicle.

Is the odometer consistent with the last reading of 38,094 on the CARFAX report summary above?

Do the tires appear to be in good shape and without uneven wear?

Test all internal controls. Do all lights, turn signals, windows and the heater and air conditioner work?

Mechanical Questions

Are the brakes and other safety equipment in good working order?

Does the vehicle appear to have been well maintained?

When should you schedule the next regular service?

Notes & Observations:

Enter your notes or additional questions here. Salesperson: Appointment Time: Price: Color:

CARFAX has estimated the remaining original manufacturer warranty coverage based on information reported to us on this 2013 CHEVROLET MALIBU LS (1G11A5SA1DF246460). Please confirm remaining factory warranty and extended warranty options with your dealer.

VIN: 1G11A5SA1DF246460

Estimated start date of warranty: 04/08/2013

Last CARFAX reading reported on 05/17/2018: 38,094 miles

Today's Date: June 16, 2018

Enter the current mileage and click 'Recalculate Warranty' to update the remaining warranty coverage.

Enter current mileage:

Recalculate Warranty

Type of Coverage: Original Warranty: Estimated Remaining Coverage:

Basic36 months or 36,000 milesCoverage expiredDrivetrain60 months or 100,000 milesCoverage expired

Emissions 96 months or 80,000 miles 34 months or 41,906 miles

Corrosion 72 months or 100,000 miles 10 months or 61,906 miles

Transferable No cost, unlimited owners covered Same

Roadside Assistance

No data reported to CARFAX

Safety belt & inflatable restraint

No data reported to CARFAX

Specific Components

No data reported to CARFAX

Notes: Emissions: Manufacturer covers emissions components under basic warranty.

Emissions coverage may vary by state. Refer to owners manual for specific details. Transferable: No cost, unlimited owners covered. Specific Components: See notes below. Maintenance: Alignment and wheel balancing are considered maintenance after 7,500 miles. 2/24,000 scheduled maintenance, 2014 and newer models. Notes: Includes surface corrosion, batteries, adjustments, alternate transportation, roadside assistance, tires prorated on 2011 and newer models. Includes courtesy transportation,

roadside assistance, transferable, no deductible.

CARFAX Warranty Check provides an **estimate** of this vehicle's remaining warranty coverage. It does not take into account some vehicle history events such as some title brands that may void the original manufacturer warranty or ownership transfers that may decrease warranty coverage. This warranty information is only valid for vehicles manufactured for the United States. Complete warranty coverage information is available for this vehicle at the CHEVROLET web site.

CARFAX Buyback Coverage
Visit https://www.mycarfax.com/bbg to register your CARFAX Buyback Guarantee and sign up for myCARFAX

Guarantee Coverage: 06/16/2018 - 06/16/2019

CARFAX Vehicle Description: 2013 CHEVROLET MALIBU LS

VIN: 1G11A5SA1DF246460 Body Style: SEDAN 4 DR

Driveline: FRONT WHEEL DRIVE Engine: 2.5L I4 F DOHC 16V

CARFAX will buy this vehicle back if you find that any of these severe problems were reported by a Départment of Motor Vehicles and were not included in this réport.

SEVERE DAMAGE

Salvage/Junk Rebuilt/Reconstructed Dismantled Fire/Flood/Hail

ODOMETER PROBLEMS

Exceeds Mechanical Limits Not Actual Mileage

LEMON HISTORY

Manufacturer Buyback

Visit the Buyback Guarantee registration page to register the CARFAX Buyback Guarantee and sign up for myCARFAX.

Terms and Conditions Apply

View Terms and Conditions for CARFAX Buyback Guarantee coverage

© 2018 CARFAX, Inc., an IHS company. All rights reserved. Patents pending. 06/16/2018 10:03:09

á % ? Ã ` ì % Áã / < % Ë Ç & / Ç { 5/30/18 {á 16060944/1 { 5/31/18 { 38096 {ã 38096 { TIMOTHY POMORSK/U543 Inventoried VPU543 IG11A5SAlDF246460

2013 CHEVROLET MALIBU 4 DOOR SILVER

#1 - MR BLW: RECONDITION USED VEHICLE FOR RESALE PER CHECKLIST

Tech: ALEX RILEY(049) M276246
Installed QFL 25 :KIT - ELEMENT & GASKET - OIL F
Installed XO 5W20 BSP :MOTORCRAFT SAE 5W-20 API GF
Sub Total: Labor: .00 Parts: .00 Total: .00
PERFORM BORGMAN LIMITED WARRANTY INSPECTION-CHANGE
D OIL AND FILTER, COMPLETED MULTIPOINT INSPECTION.
PLUGED A HOLE IN THE LR TIRE FROM A NAIL, FOR INFO
ON THE BRAKE PULSE SEE LINE 2.
FRONT TIRE TREAD DEPTH IS 6/32''
REAR TIRE TREAD DEPTH IS 7/32''
ALL BRAKE PADS ARE AT 7MM

Internal Internal Internal

ALL BRAKE FADS ARE AT /MM

#2 - MR USED: USED CAR DEPARTMENT

PULSE
Caused by
PULSE??

Tech: ALEX RILEY(049) M276246
Sub Total: Labor: .00 Parts: .00 Total: .00
I TEST DROVE THE VEHICLE AND WAS ABLE TO VERIFY TH
E BRAKE PULSE, I THEN INSPECTED THE BRAKE SYSTEM A
ND AT THIS TIME I BELIVE IT TO BE SURFACE RUST ON
ALL OF THE BRAKE ROTORS AND SHOULD DISAPATE WHILE
DRIVING THE VEHICLE. WHILE I WAS ON THE TEST DRIV
E THE BRAKE PUSLED WORSE IN THE BEGGINING OF THE D
RIVE AND TWARD THE END OF IT THE BRAKE PULSE WAS H
ARDLY NOTICEABLE.

Internal

á % ? Ã ` ì % Áã / < % Ë Ç & / Ç { 5/30/18 {á 16060944/2 { 5/31/18 { 38096 {ã 38096 { TIMOTHY POMORSK/U543 Inventoried VPU543 IG11A5SAlDF246460

2013 CHEVROLET MALIBU 4 DOOR SILVER

#3 - MR USEDR: CHECK USED VEHICLE FOR RECALLS
NO OPEN RECALLS AS OF 5/30/18
Tech: ALEX RILEY(049) M276246
CHECKED VEHICLE FOR RECALLS AND FOUND NONE

Internal

.00