Repair Order Detail - Customer Copy

RO Number: 458322 RO Status: CLOSED

Customer: DAN PERKINS SUBARU

Phone(s): Contact: (203)878-4621

Vehicle: 4S3GKAA61P1601424

Main: (203)878-4621 2023 IMPR

Cell:

Mileage: 7,061

Service advisor: 437

Payment type: CASH

Promised time: 08:00 PM

Waiter: No

DNH@A.COM

Estimate:

0.00

Promised date: 10/02/2025 Tag number: T212121

~~~	.~~~~~	~~~~~~	~~~~~~~~~~~~~~~~~~~	~~~~~~~~~~~~	~~~~
Α	SAFET	Y CHECK & C	OIL AND FILTER CHANGE AND CH	HECK ALL FLUIDS	
S	CLOF	IUC SAFETY CHECK & OIL			N/C
			AND FILTER CHANGE AND		
	To ab (a).	CE	CHECK ALL FLUIDS		
	Tech(s): 65 15208AA21A		1 ELEM CP-OIL FLTR		N/C
	SOA635045		6 OIL 0W20 SYNTH		N/C
	8039160		1 GASKET		N/C
Pts:		0.00 Lbr:		0.00 Total Line A:	0.00
~~~ B	 DMV SH	~~~~~~ HEET	~~~~~~~~~~~~	~~~~~~~~~~	·~~~
	MV		DMV SHEET		N/C
	Tech(s):	65			
Pts:		0.00 Lbr:	0.00 Other:	0.00 Total Line B:	0.00
C**	CERTIFIED PRE-OWNED VEHICLE INSPECTION				
С	PO		CERTIFIED PRE-OWNED		N/C
			VEHICLE INSPECTION		
Dtai	Tech(s):		0.00. Other	0.00 Tatallina C	0.00
Pts:	~~~~~	0.00 Lbr:	0.00 Other:	0.00 Total Line C:	0.00
	Customer Pay Labor				
					0.00
Parts Lube					0.00
Sublet Miscellaneous/Shop Charge Deductible Total Charges Less Insurance/Adjustment					0.00 0.00
					0.00
					0.00
					0.00
					0.00
			Sales Tax Total		0.00
			0.00		