

Repair Order Detail - Customer Copy

RO Number: 466947

RO Status: CLOSED

Customer: DAN PERKINS SUBARU

NOEMAIL.EMAIL@EMAIL.COM

Phone(s): Contact: (203)882-5686

Main: (203)882-5686

Cell: (914)384-2574

Vehicle: 4S4BTGND0L3143887

2020 OUTB

GRAY

Mileage: 78,435

Payment type: CASH

Waiter: No

Service advisor: 290

Promised time: 08:00 PM

Estimate: 0.00

Tag number: T887

Promised date: 02/17/2026

~~~~~  
A SAFETY CHECK & OIL AND FILTER CHANGE AND CHECK ALL FLUIDS  
SCLOF IUC SAFETY CHECK & OIL AND FILTER CHANGE AND CHECK ALL FLUIDS N/C  
Tech(s): 270  
15208AA21A 1 ELEM CP-OIL FLTR N/C  
SOA635045 6 OIL 0W20 SYNTH N/C  
803916010 1 GASKET N/C  
Pts: 0.00 Lbr: 0.00 Other: 0.00 Total Line A: 0.00  
Story: 78435 PERFORM LUBE OIL AND FILTER CHANGE WITH GENUINE SUBARU PARTS AND FLUIDS  
~~~~~

B DMV SHEET
DMV IUC PASS N/C
Tech(s): 270
Pts: 0.00 Lbr: 0.00 Other: 0.00 Total Line B: 0.00
~~~~~

C NO OPEN RECALLS AS OF TODAY  
NR IUC NO OPEN RECALLS AS OF TODAY N/C  
Tech(s): 270  
Pts: 0.00 Lbr: 0.00 Other: 0.00 Total Line C: 0.00  
~~~~~

D** MOUNT AND BALANCE 4 TIRE
MB4 IUC MOUNT AND BALANCE 4 TIRE N/C
Tech(s): 270
MISC 1 SUMMIT TRAIL CLIMBER SUV(TFT) N/C
WWT 1 WHEEL WEIGHT N/C
Pts: 0.00 Lbr: 0.00 Other: 0.00 Total Line D: 0.00
Story: 78435 replaced all tires
~~~~~

E\*\* 4 WHEEL ALIGNMENT. INSPECT/ADJUST CASTER, CAMBER & TOE, INSPECT SUSPENSION & STEERING. TECH ROAD TESTED.  
ALIGN IUC 4 WHEEL ALIGNMENT. INSPECT/ADJUST CASTER, CAMBER & TOE, INSPECT SUSPENSION & STEERING. TECH ROAD TESTED. N/C  
Tech(s): 270  
Pts: 0.00 Lbr: 0.00 Other: 0.00 Total Line E: 0.00  
Story: 78435 PERFORM FULL FOUR WHEEL ALIGNMENT AND PERFORM QUALITY ROAD TEST  
~~~~~

Repair Order Detail - Customer Copy

RO Number: 466947

RO Status: CLOSED

Customer: DAN PERKINS SUBARU

NOEMAIL.EMAIL@EMAIL.COM

Phone(s): Contact: (203)882-5686

Main: (203)882-5686

Cell: (914)384-2574

Vehicle: 4S4BTGND0L3143887

2020 OUTB

GRAY

Mileage: 78,435

Payment type: CASH

Waiter: No

Service advisor: 290

Promised time: 08:00 PM

Estimate: 0.00

Tag number: T887

Promised date: 02/17/2026

```

~~~~~
F**  TECH NOTED THE LOWER CONTROL ARM BUSHINGS NEED TO BE REPLACE
00      IUC      REPLACE THE LOWER CONTROL ARM BUSHINGS N/C

Tech(s): 270
20204AG030      2 BUSHING TRANSVERSE LINK F N/C
20204FL020      2 BUSHING TRANSVERSE LINK R N/C
051030300      2 COTTER PIN N/C
SOA635041      4 SUPER COOLANT N/C
Pts:          0.00 Lbr:          0.00 Other:          0.00 Total Line F:          0.00
Story: 78435  replaced front lca bushings
    
```

```

~~~~~
G**  SUBARU ENGINE AIR FILTER
AIR      IUC      SUBARU ENGINE AIR FILTER N/C

Tech(s): 270
16546AA16A      1 ELEMENT AIR CLEANER N/C
Pts:          0.00 Lbr:          0.00 Other:          0.00 Total Line G:          0.00
Story: 78435  replaced filter
    
```

```

~~~~~
H**  SUBARU CABIN AIR FILTER $94.99
CABIN      IUC      SUBARU CABIN AIR FILTER $94.99 N/C

Tech(s): 270
72880FL00A      1 FILTER N/C
Pts:          0.00 Lbr:          0.00 Other:          0.00 Total Line H:          0.00
Story: 78435  replaced filter
    
```

```

~~~~~
Customer Pay
Labor          0.00
Parts          0.00
Lube          0.00
Sublet        0.00
Miscellaneous/Shop Charge 0.00
Deductible    0.00
Total Charges 0.00
Less Insurance/Adjustment 0.00
Sales Tax     0.00
Total         0.00
    
```