

Repair Order Detail - Customer Copy

RO Number: 460103

RO Status: CLOSED

Customer:

Phone(s): Contact: (203)882-5686

Main:

Cell:

Vehicle: 4S3GTAA67J3722547

2018 IMPR

Mileage: 108,634

Payment type: CASH

Waiter: No

Service advisor: 911

Promised time: 08:00 PM

Estimate: 0.00

Tag number: T22547

Promised date: 10/30/2025

~~~~~  
A SAFETY CHECK & ADVISE  
SCLOF IUC SAFETY CHECK & OIL N/C  
AND FILTER CHANGE AND  
CHECK ALL FLUIDS

Tech(s): 29

15208AA21A

1 ELEM CP-OIL FLTR

N/C

SOA635045

6 OIL 0W20 SYNTH

N/C

803916010

1 GASKET

N/C

32195AA021

1 PLUG OIL DRAIN

N/C

Pts: 0.00 Lbr: 0.00 Other: 0.00 Total Line A: 0.00

Story: 108634 150 performed safety & lof

~~~~~  
B NO OPEN RECALL AS OF TODAY
NR IUC NO OPEN RECALL AS OF N/C
TODAY

Tech(s): 29

Pts: 0.00 Lbr: 0.00 Other: 0.00 Total Line B: 0.00

~~~~~  
C DMV SHEET  
DMV IUC DMV SHEET N/C

Tech(s): 29

Pts: 0.00 Lbr: 0.00 Other: 0.00 Total Line C: 0.00

~~~~~  
D** REMOVE AND REPLACE WIPER
WIPER IUC REPLAED ALL WIPER N/C
BLADES FRONT AND RR

Tech(s): 29

SOA591B716

1 16" BEAM WIPER BLADE
(PAS

N/C

SOA591B726

1 PB001826 26" BEAM
WIPER B

N/C

SOA591R612

1 12" REAR WIPER BLADE

N/C

Pts: 0.00 Lbr: 0.00 Other: 0.00 Total Line D: 0.00

Story: 108634 20 replaced wipers

~~~~~  
E\*\* REPPLACE DRIVE BELT  
BELT IUC REMOVED AND REPLACED N/C  
DRIVE BELT

Tech(s): 29

23780AA08A

1 V BELT

N/C

Pts: 0.00 Lbr: 0.00 Other: 0.00 Total Line E: 0.00

Story: 108634 70 replaced drive belt

~~~~~  
F** SUBARU ENGINE AIR FILTER
AIR IUC REMOVED AND REPLACED N/C

Repair Order Detail - Customer Copy

RO Number: 460103

RO Status: CLOSED

Customer:

Phone(s): Contact: (203)882-5686
Vehicle: 4S3GTAA67J3722547

Main:
2018 IMPR

Cell:

Mileage: 108,634
Service advisor: 911
Tag number: T22547

Payment type: CASH
Promised time: 08:00 PM
Promised date: 10/30/2025

Waiter: No
Estimate: 0.00

~~~~~  
AIR FILTER

Tech(s): 29

72880FL00A

1 FILTER

N/C

Pts: 0.00 Lbr: 0.00 Other: 0.00 Total Line F: 0.00

Story: 108634 30 replaced air filter

~~~~~  
G** CABIN AIR FILTER

CABIN

IUC

REMOVED AND REPLACED
CABIN AIR FILTER

N/C

Tech(s): 29

72880FL00A

1 FILTER

N/C

Pts: 0.00 Lbr: 0.00 Other: 0.00 Total Line G: 0.00

Story: 108634 30 replaced cabin filter

~~~~~  
H\*\* REPAIR HEAT SHIELD RATTLE

HEAT

IUC

REPAIRED HEAT SHEILD  
RATTLE UNDERNEATH  
VEHICLE

N/C

Tech(s): 29

CLAMP

1 EXHCLAMP

N/C

Pts: 0.00 Lbr: 0.00 Other: 0.00 Total Line H: 0.00

Story: 108634 50 resecured heat shields

~~~~~  
I** 4 SPARK PLUGS REPLACEMENT. (TURBO AND OR 4 CYLINDER)

SPARK4

IUC

REMOVED AND REPLACED
ALL SPARK PLUGS

N/C

Tech(s): 29

22401AA880

4 SPARK PLUG

N/C

Pts: 0.00 Lbr: 0.00 Other: 0.00 Total Line I: 0.00

Story: 108634 200 replaced spark plugs

~~~~~  
J\*\* MOUNT AND BALANCE 4 TIRE

MB4

IUC

MOUNTED AND BALANCED  
4 TIRES

N/C

Tech(s): 29

28141SA556

4 2055516 ATREZZO SH408

N/C

WWT

1 WHEEL WEIGHT

N/C

ST

4 TIRE DISPOSAL

N/C

28194FJ001

1 TPMS STEM AY

N/C

Pts: 0.00 Lbr: 0.00 Other: 0.00 Total Line J: 0.00

Story: 108634 100 mounted 4 tires

~~~~~  
K** REMOVE AND REPLACE FRONT LOWER CONTROL ARM BUSHINGS

00

IUC

REMOVED LOWER

Repair Order Detail - Customer Copy

RO Number: 460103

RO Status: CLOSED

Customer:

Phone(s): Contact: (203)882-5686

Main:

Cell:

Vehicle: 4S3GTAA67J3722547

2018 IMPR

Mileage: 108,634

Payment type: CASH

Waiter: No

Service advisor: 911

Promised time: 08:00 PM

Estimate: 0.00

Tag number: T22547

Promised date: 10/30/2025

~~~~~  
CONTROL

N/C

ARMS AND PRESSED IN

NEW BUSHINGS

Tech(s): 29

20204FL01B

2 RUB BUSH ARM F R

N/C

20204AG030

2 BUSHING TRANSVERSE

N/C

LINK F

Pts: 0.00 Lbr: 0.00 Other: 0.00 Total Line K: 0.00

Story: 108634 400 replaced control arm bushings

~~~~~  
L** 4 WHEEL ALIGNMENT. INSPECT/ADJUST CASTER, CAMBER & TOE, INSPECT
SUSPENSION & STEERING. TECH ROAD TESTED.

ALIGN

IUC

4 WHEEL ALIGNMENT.

N/C

INSPECT/ADJUST

CASTER, CAMBER & TOE,

INSPECT SUSPENSION &

STEERING. TECH ROAD

TESTED.

Tech(s): 29

Pts: 0.00 Lbr: 0.00 Other: 0.00 Total Line L: 0.00

Story: 108634 100 PERFORM FULL FOUR WHEEL ALIGNMENT AND PERFORM
QUALITY ROAD TEST

~~~~~  
Customer Pay

Labor

0.00

Parts

0.00

Lube

0.00

Sublet

0.00

Miscellaneous/Shop Charge

0.00

Deductible

0.00

Total Charges

0.00

Less Insurance/Adjustment

0.00

Sales Tax

0.00

Total

0.00