Repair Order Detail - Customer Copy

Waiter: No

RO Number: 461110 RO Status: CLOSED

Customer: DAN PERKINS SUBARU

NOEMAIL@EMAIL.COM Main: (203)882-5686 Phone(s): Contact: (203)882-5686 Cell:

Vehicle: 2HKRS4H43PH408974

Mileage: 17,248

2023 CRV

Payment type: CASH

Promised time: 08:00 PM Service advisor: 911 Estimate: 0.00

Tag number: T08974 Promised date: 11/14/2025

~~~	-~~~~	~~~~~~~	~~~~~~~~~~	~~~~~~~~~~~	-~~~
Α					
S	CLOF	IUCN	PERFORMED SAFETY		N/C
	INSPECTION, CHANGED				
	ENGINE OIL AND FILTER, CHECKED ALL				
	FLUIDS				
	Tech(s): 87 15400PLMA02		1 OIL FILTER HO	NIDA	N/C
	134001 LIVIAUZ			GENUINE	
	OR		1 ORING		N/C
	SOA635045			6 OIL 0W20 SYNTH	
Pts:			0.00 Other:		0.00
~~~	~~~~~			~~~~~~~~	~~~~
	NO OPEN RECALL AS OF TODAY				
N	R		NO OPEN RECALL AS OF		N/C
	Tooh(o):		TODAY		
Pts:		87 0.00 l.br:	0.00 Other:	0.00 Total Line B:	0.00
~~~	~~~~~	~~~~~~~	0.00 Other.	0.00 Total Line B.	0.00
	Customer Pay				
Labor Parts			Labor		0.00
				0.00	
			Lube		0.00
	Sublet				0.00
	Miscellaneous/Shop Charge Deductible Total Charges Less Insurance/Adjustment			Charge	0.00
					0.00 0.00
				stment	0.00
Sales Tax				Sunent	0.00
			Total		0.00
			iolai		0.00