

# Repair Order Detail - Customer Copy

RO Number: 461407

RO Status: CLOSED

Customer: DAN PERKINS SUBARU

Phone(s): Contact: (203)882-5686

Vehicle: 4S3GTAA69P1720402

Main: (203)882-5686

2023 IMPR

[NOEMAIL@EMAIL.COM](mailto:NOEMAIL@EMAIL.COM)

Cell:

Mileage: 24,739

Service advisor: 911

Tag number: T20402

Payment type: CASH

Promised time: 08:00 PM

Promised date: 11/20/2025

Waiter: No

Estimate: 0.00

~~~~~  
A      PERFORM CERTIFIED SAFETY INSPECTION WITH CERTIFIED SAFETY  
         BOOKLET, PERFORM ENGINE OIL AND FILTER CHANGE  
SCLOF      IUC      PERFORMED CERTIFIED      N/C  
                         SAFETY INSPECTION  
                         WITH BOOKLET, CHANGED  
                         ENGINE OIL AND FILTER

Tech(s): 65  
15208AA21A      1 ELEM CP-OIL FLTR      N/C  
SOA635045      6 OIL 0W20 SYNTH      N/C  
803916010      1 GASKET      N/C  
Pts:      0.00 Lbr:      0.00 Other:      0.00 Total Line A:      0.00

~~~~~  
B      DMV SHEET  
DMV      IUC      DMV SHEET      N/C

Tech(s): 65  
Pts:      0.00 Lbr:      0.00 Other:      0.00 Total Line B:      0.00

~~~~~  
C      NO OPEN RECALL AS OF TODAY  
NR      IUC      NO OPEN RECALL AS OF      N/C  
                         TODAY

Tech(s): 65  
Pts:      0.00 Lbr:      0.00 Other:      0.00 Total Line C:      0.00

~~~~~  
D\*\*      SUBARU ENGINE AIR FILTER  
AIR      IUC      REPLACED ENGINE AIR      N/C  
                         FILTER

Tech(s): 65  
16546AA210      1 PB001983 ELEMENT-AIR      N/C  
                         CLNR  
Pts:      0.00 Lbr:      0.00 Other:      0.00 Total Line D:      0.00

~~~~~  
E\*\*      REPLACE CABIN AIR FILTER  
CABIN      IUC      REPLACED CABIN AIR      N/C  
                         FILTER

Tech(s): 65  
72880FL00A      1 FILTER      N/C  
Pts:      0.00 Lbr:      0.00 Other:      0.00 Total Line E:      0.00

~~~~~  
F\*\*      4 WHEEL ALIGNMENT. INSPECT/ADJUST CASTER, CAMBER & TOE, INSPECT  
         SUSPENSION & STEERING. TECH ROAD TESTED.  
ALIGN      IUC      4 WHEEL ALIGNMENT.      N/C  
                         INSPECT/ADJUST  
                         CASTER, CAMBER & TOE,  
                         INSPECT SUSPENSION &  
                         STEERING. TECH ROAD

# Repair Order Detail - Customer Copy

RO Number: 461407

RO Status: CLOSED

Customer: DAN PERKINS SUBARU

[NOEMAIL@EMAIL.COM](mailto:NOEMAIL@EMAIL.COM)

Phone(s): Contact: (203)882-5686

Main: (203)882-5686

Cell:

Vehicle: 4S3GTAA69P1720402

2023 IMPR

Mileage: 24,739

Payment type: CASH

Waiter: No

Service advisor: 911

Promised time: 08:00 PM

Estimate: 0.00

Tag number: T20402

Promised date: 11/20/2025

~~~~~  
TESTED.

Tech(s): 65

Pts: 0.00 Lbr: 0.00 Other: 0.00 Total Line F: 0.00  
~~~~~

Customer Pay

Labor

0.00

Parts

0.00

Lube

0.00

Sublet

0.00

Miscellaneous/Shop Charge

0.00

Deductible

0.00

Total Charges

0.00

Less Insurance/Adjustment

0.00

Sales Tax

0.00

Total

0.00