

Repair Order Detail - Customer Copy

RO Number: 459852

RO Status: CLOSED

Customer: DAN PERKINS SUBARU

Phone(s): Contact: (203)878-4621

Vehicle: JHMFL5G42SX002171

Main: (203)878-4621

2025 CIVI

BLUE

DNH@A.COM

Cell:

Mileage: 1,563

Service advisor: 437

Tag number: T6456456

Payment type: CASH

Promised time: 08:00 PM

Promised date: 10/27/2025

Waiter: No

Estimate: 0.00

~~~~~  
A SAFETY CHECK & OIL AND FILTER CHANGE AND CHECK ALL FLUIDS  
SCLOF IUCN SAFETY CHECK & OIL AND FILTER CHANGE AND CHECK ALL FLUIDS N/C

Tech(s): 23

15400PLMA02

1 OIL FILTER HONDA

GENUINE

N/C

SOA635045

6 OIL 0W20 SYNTH

N/C

Pts: 0.00 Lbr: 0.00 Other: 0.00 Total Line A: 0.00

Story: 1563 PERFORM LUBE OIL AND FILTER CHANGE WITH GENUINE  
SUBARU PARTS AND FLUIDS

~~~~~  
B DMV SHEET
DMV IUCN DMV SHEET N/C

Tech(s): 23

Pts: 0.00 Lbr: 0.00 Other: 0.00 Total Line B: 0.00

~~~~~  
C CERTIFIED PRE-OWNED VEHICLE INSPECTION  
CPO IUCN CERTIFIED PRE-OWNED VEHICLE INSPECTION N/C

Tech(s): 23

Pts: 0.00 Lbr: 0.00 Other: 0.00 Total Line C: 0.00

~~~~~  
Customer Pay
Labor 0.00
Parts 0.00
Lube 0.00
Sublet 0.00
Miscellaneous/Shop Charge 0.00
Deductible 0.00
Total Charges 0.00
Less Insurance/Adjustment 0.00
Sales Tax 0.00
Total 0.00