Repair Order Detail - Customer Copy

RO Number: 451135 RO Status: CLOSED

Customer: DAN PERKINS SUBARU DNH@A.COM
Phone(s): Contact: (203)878-4621 Main: (203)878-4621 Cell:
Vehicle: JF2GUHDC7SH283315 2025 CRTK WHITE

Mileage: 7 Payment type: CASH Waiter: No
Service advisor: 437 Promised time: 08:00 PM Estimate: 0.00
Tag number: T986321 Promised date: 06/20/2025

~~~~~~

A PRE DELIVERY INSPECTION

PDI1	WPDI	PRE DELIVERY INSPECTION	N/C

Tech(s): 76

Pts: 0.00 Lbr: 0.00 Other: 0.00 Total Line A: 0.00

~~~~~~

B NO OPEN RECALL AS OF TODAY

NR	IUC	NO OPEN RECALL AS OF TODAY	N/C

Tech(s): 76

Pts: 0.00 Lbr: 0.00 Other: 0.00 Total Line B: 0.00

~~~~~~

Customer Pay	
Labor	0.00
Parts	0.00
Lube	0.00
Sublet	0.00
Miscellaneous/Shop Charge	0.00
Deductible	0.00
Total Charges	0.00
Less Insurance/Adjustment	0.00
Sales Tax	0.00
Total	0.00
~~~~~~