

Repair Order Detail - Customer Copy

RO Number: 459628

RO Status: CLOSED

Customer: DAN PERKINS SUBARU

Phone(s): Contact: (203)882-5686

Vehicle: 1C4RJFBG4MC563302

Main: (203)882-5686

2021 GRANC

NOEMAIL@EMAIL.COM

Cell:

Mileage: 37,956

Service advisor: 397

Tag number: T563302

Payment type: CASH

Promised time: 08:00 PM

Promised date: 10/23/2025

Waiter: No

Estimate: 0.00

~~~~~  
A SAFETY CHECK & OIL AND FILTER CHANGE AND CHECK ALL FLUIDS  
SCLOF IUCN SAFETY CHECK & OIL AND FILTER CHANGE AND CHECK ALL FLUIDS N/C

Tech(s): 87  
WIXWL10010 1 WIX OIL FILTER N/C  
SOA635044 6 OIL 5W30 SYNTH N/C  
OR 1 ORING N/C  
Pts: 0.00 Lbr: 0.00 Other: 0.00 Total Line A: 0.00  
~~~~~

B DMV SHEET
DMV IUCN DMV PASS N/C

Tech(s): 87
Pts: 0.00 Lbr: 0.00 Other: 0.00 Total Line B: 0.00
~~~~~

C\*\* REAR BRAKE SERVICE: PADS & ROTORS  
RBJR IUCN REAR BRAKE SERVICE: PADS & ROTORS N/C

Tech(s): 87  
MISC 1 RR PADS (CQ) N/C  
MISC 2 RR ROTORS (CQ) N/C  
T20 1 BRAKEKLEEN NON-CHLOR N/C  
SOA635334 1 DOT 3 BRAKE FLUID N/C  
Pts: 0.00 Lbr: 0.00 Other: 0.00 Total Line C: 0.00  
~~~~~

D** FRONT WIPER REPLACEMENT (2X)
WIPER IUCN FRONT WIPER REPLACEMENT (2X) N/C

Tech(s): 87
MISC 2 FR WIPERS (CQ) N/C
Pts: 0.00 Lbr: 0.00 Other: 0.00 Total Line D: 0.00
~~~~~

E\*\* REAR WIPER REPLACEMENT  
WIPERR IUCN REAR WIPER REPLACEMENT N/C

Tech(s): 87  
MISC 1 RR WIPER (CQ) N/C  
Pts: 0.00 Lbr: 0.00 Other: 0.00 Total Line E: 0.00  
~~~~~

Customer Pay

Labor 0.00

Parts 0.00

Lube 0.00

Sublet 0.00

Repair Order Detail - Customer Copy

Miscellaneous/Shop Charge	0.00
Deductible	0.00
Total Charges	0.00
Less Insurance/Adjustment	0.00
Sales Tax	0.00
Total	0.00