Repair Order Detail - Customer Copy

RO Number: 459433 RO Status: CLOSED

Customer: DAN PERKINS SUBARU

NOEMAIL@EMAIL.COM

Phone(s): Contact: (203)882-5686

Main: (203)882-5686 Cell:

Vehicle: JF2GUADC3RH208645

2024 CRTK WHITE

Mileage: 54,965

Payment type: CASH

Service advisor: 911

Payment type: CASH Waiter: No Promised time: 08:00 PM Estimate: 0.00

Tag number: T208645 Promised date: 10/21/2025

rag n	difficor. 120	70040	r romiloca dato.	. 10/21/2020		
	PERFO CHANG		FIED SAFETY INSPEC	TION WITH SA	AFETY BOOLKET AD OIL	~~
	CLOF		PERFORMED CERTII SAFETY INSPECTON ENGINE OIL AND FIL CHANGE WITH CERT BOOKLET	I TER		N/C
	Tech(s):					
	15208AA SOA635			CP-OIL FLTR SYNTHETIC M	IOTOR	N/C N/C
	8039160		1 GASKE			N/C
Pts:		0.00 Lbr:	0.00 Other:	(0.00 Total Line A:	0.00
B	DMV SH	~~~~~~~ I EET	~~~~~~~	~~~~~~	~~~~~~~~~~	~~
D	MV Table (a)	IUC	DMV SHEET			N/C
Pts:	Tech(s):	0.00 Lbr:	0.00 Other:	(0.00 Total Line B:	0.00
			S OF TODAY	~~~~~~	~~~~~~~~~~	~~
			NO OPEN RECALL AS TODAY	S OF		N/C
	Tech(s):		0.00 Other:		0.00 Total Line C:	0.00
			VICE: PADS & ROTORS		~~~~~~~~~~	~~
Fi	3JR	IUC	REMOVED AND REP FRONT BRAKE PADS ROTORS			N/C
	Tech(s):	275	KOTOKO			
	26300FN		2 BRAKE			N/C
Pts:	26296FN	0.00 Lbr:	1 PAD KIT 0.00 Other:		0.00 Total Line D:	N/C 0.00
~~~ E**	REAR E	RAKE SERV	CE: PADS & ROTORS	~~~~~		~~
R	BJR	IUC	RPLACED REAR BRA PADS AND ROTORS	AKE		N/C
	Tech(s):		O DDAKE	DICC D		N/O
	26700SJ 26696VC		2 BRAKE 1 PAD KI			N/C N/C
	T20		2 BRAKE	KLEEN NON-C		N/C
Pts:		0.00 Lbr:	0.00 Other:	(	0.00 Total Line E:	0.00
~~~ F**			FILTER \$94.99			~~
	ABIN Created: 11/02/2	IUC 025 04:10:59 PM	REMOVED AND REP	LACED		N/C

Repair Order Detail - Customer Copy

RO Number: 459433 RO Status: CLOSED

Customer: DAN PERKINS SUBARU NOEMAIL@EMAIL.COM

Phone(s): Contact: (203)882-5686 Main: (203)882-5686 Cell:

Vehicle: JF2GUADC3RH208645 2024 CRTK WHITE

Mileage: 54,965 Payment type: CASH Waiter: No

Service advisor: 911 Promised time: 08:00 PM Estimate: 0.00

Tag number: T208645)8645	Promised date: 10/21/2025			
~~	CAABIN AIR FILTER					
	Tech(s):					
Dia	16546AA		1 ELEMENT AIR CLEANER	N/C		
Pts:	~~~~~	0.00 Lbr: ~~~~~~	0.00 Other: 0.00 Total Line F:	0.00		
G**		U ENGINE AI		N/O		
Α	MK	IUC	REMOVED AND REPLACED AIR FILTER	N/C		
	Tech(s):					
	72880FN		1 FILTER	N/C		
Pts:	~~~~~~	0.00 Lbr:	0.00 Other: 0.00 Total Line G:	0.00		
		WIPER REP	LACEMENT (2X)			
V	VIPER	IUC	REMOVED AND REPLACED	N/C		
	Tech(s):	275	FRONT WIPER BLADES			
	SOA591		1 PB001826 26" BEAM	N/C		
			WIPER B			
	SOA591	3716	1 16" BEAM WIPER BLADE (PAS	N/C		
Pts:		0.00 Lbr:	0.00 Other: 0.00 Total Line H:	0.00		
~~. **	RFAR V	~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~				
V			REMOVED AND REPLACED REAR WIPER	N/C		
	Tech(s):					
Dia	SOA591		1 12" REAR WIPER BLADE	N/C		
Pts:	~~~~~~	0.00 Lbr:	0.00 Other: 0.00 Total Line I:	0.00		
J**	CUSTO IN DRIV		S CHECK AND ADVISE ON LEAK- STATES HAS SEEN SPOTS			
2	43602	W	LH CAMSHAFT COVER, SEAL/GASKET R&R	N/C		
	Tech(s):					
	22401AA		2 SPARK PLUG	N/C N/C		
	10966AA		2 GSKT-SPARK PL PIP			
_	13272AA		1 GASKET ROCKER COVER LH	N/C		
2	45001	W	OIL &/OR COOLANT LEAK TESTING & DIAG	N/C		
	Tech(s):	275	12011110 0 2 1110			
Pts:	()	0.00 Lbr:	0.00 Other: 0.00 Total Line J:	0.00		
Story: 54965 UPON INPSECTION FOUND OIL LEAKING FROM SPARK PLUG TUBE						
			ced drivers front valve cover			
	SK et due to t , Created: 11/02/2		s leaking from the spark plug			

Repair Order Detail - Customer Copy

RO Number: 459433 RO Status: CLOSED

Customer: DAN PERKINS SUBARU

NOEMAIL@EMAIL.COM Main: (203)882-5686

Phone(s): Contact: (203)882-5686

Cell:

Vehicle: JF2GUADC3RH208645

2024 CRTK WHITE

Mileage: 54,965

Payment type: CASH

Waiter: No

Service advisor: 911 Tag number: T208645 Promised time: 08:00 PM Promised date: 10/21/2025

Estimate: 0.00

tube seals, replaced valve cover gasket with tube seals and

2 spark plugs on the drivers side

Customer Pay	
Labor	0.00
Parts	0.00
Lube	0.00
Sublet	0.00
Miscellaneous/Shop Charge	0.00
Deductible	0.00
Total Charges	0.00
Less Insurance/Adjustment	0.00
Sales Tax	0.00
Total	0.00