

# Repair Order Detail - Customer Copy

RO Number: 457755

RO Status: CLOSED

Customer:

Phone(s): Contact: (203)882-5686

Main:

Cell:

Vehicle: KM8K2CAA7JU147885

2018 KONA

Mileage: 89,770

Payment type: CASH

Waiter: No

Service advisor: 911

Promised time: 08:00 PM

Estimate: 0.00

Tag number: T7885

Promised date: 09/24/2025

~~~~~  
A SAFETY CHECK & ADVISE

SCAA IUCN SAFETY CHECK & ADVISE N/C

Tech(s): 65

WIX51334

1 WIX OIL FILTER

N/C

SOA635044

5 OIL 5W30 SYNTH

N/C

Pts: 0.00 Lbr: 0.00 Other: 0.00 Total Line A: 0.00  
~~~~~

B NO RECALL AT THIS TIME

NR IUCN NO OPEN RECALL AS OF TODAY N/C

Tech(s): 65

Pts: 0.00 Lbr: 0.00 Other: 0.00 Total Line B: 0.00  
~~~~~

C\*\* REMOVE AND REPLACE ENGINE

00 IUCN REMOVED AND REPLACED ENGINE ASSEMBLY N/C

Tech(s): 65

MISC

1 110K ENGINE

N/C

OR

1 ORING

N/C

SOA635310

1 FREON 1234YF

N/C

Pts: 0.00 Lbr: 0.00 Other: 0.00 Total Line C: 0.00  
~~~~~

D\*\* MOUNT AND BALANCE 4 TIRE

MB4 IUCN MOUNT AND BALANCE 4 TIRE N/C

Tech(s): 65

MISC

4 215/55R17 ARROYOS

N/C

WWT

1 WHEEL WEIGHT

N/C

ST

4 TIRE DISPOSAL

N/C

Pts: 0.00 Lbr: 0.00 Other: 0.00 Total Line D: 0.00  
~~~~~

E\*\* 4 WHEEL ALIGNMENT. INSPECT/ADJUST CASTER, CAMBER & TOE, INSPECT  
SUSPENSION & STEERING. TECH ROAD TESTED.

ALIGN IUCN 4 WHEEL ALIGNMENT. INSPECT/ADJUST CASTER, CAMBER & TOE, INSPECT SUSPENSION & STEERING. TECH ROAD TESTED. N/C

Tech(s): 65

Pts: 0.00 Lbr: 0.00 Other: 0.00 Total Line E: 0.00  
~~~~~

Customer Pay  
Labor

0.00

# Repair Order Detail - Customer Copy

|                           |      |
|---------------------------|------|
| Parts                     | 0.00 |
| Lube                      | 0.00 |
| Sublet                    | 0.00 |
| Miscellaneous/Shop Charge | 0.00 |
| Deductible                | 0.00 |
| Total Charges             | 0.00 |
| Less Insurance/Adjustment | 0.00 |
| Sales Tax                 | 0.00 |
| Total                     | 0.00 |