Repair Order Detail - Customer Copy

RO Number: 460299 RO Status: CLOSED

Customer: DAN PERKINS SUBARU

NOEMAIL@EMAIL.COM Cell:

Main: (203)882-5686 Phone(s): Contact: (203)882-5686 2025 COLOR **WHITE**

Vehicle: 1GCPTBEK4S1110848

Mileage: 15,413 Payment type: CASH Waiter: No

Service advisor: 290 Promised time: 08:00 PM Estimate: 0.00

Promised date: 11/03/2025 Tag number: T60

~.	~~~~~~	~~~~~~	~~~~~~~~~~~~~~~	~~~~~~~~~~~	~~~	
A SAFETY CHECK & OIL AND FILTER CHANGE AND CHECK ALL FLUIDS						
	SCLOF	IUCN			N/C	
	AND FILTER CHANGE AND					
	-	~	CHECK ALL FLUIDS			
	Tech(s): 87		0.00.574/00.07/	NITLI	N/C	
	SOA635	044		6 OIL 5W30 SYNTH		
	MISC		1 WIXWL10351		N/C	
D4-	OR	0.00 11	1 ORING	0.00 Tatallia - A.	N/C	
Pts:		0.00 Lbr:	0.00 Other:	0.00 Total Line A:	0.00	
~ ⁄ B	DMV SI	~~~~~~~ HEET	~~~~~~~~~~~~~~	~~~~~~~~~~~~~~~~~~~	~~~	
	DMV		PASS		N/C	
	Tech(s):					
Pts:		0.00 Lbr:	0.00 Other:	0.00 Total Line B:	0.00	
~	~~~~~~~	~~~~~~~~		~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~	~~~	
			S PERFORM ANY OPEN REC CUSTOMER STATES	ALL	N/C	
	RECALL	ECALL IUCN CUSTOMER STATES PERFORM ANY OPEN			IN/C	
			RECALL			
	Tech(s):	87	NEOALL			
Pts:			0.00 Other:	0.00 Total Line C:	0.00	
~	· ~~~~~~~	~~~~~~	~~~~~~~~~~~~	~~~~~~~~~~~~~~~~~	0.00 ~~~	
			Customer Pay			
			Labor		0.00	
			Parts		0.00	
			Lube		0.00	
			Sublet		0.00	
			Miscellaneous/Sho	Miscellaneous/Shop Charge		
			Deductible			
			Total Charges	Total Charges		
			Less Insurance/Adjustment		0.00	
			Sales Tax		0.00	
			Total		0.00	