

# Repair Order Detail - Customer Copy

RO Number: 461678

RO Status: CLOSED

Customer: DAN PERKINS SUBARU

Phone(s): Contact: (203)882-5686

Vehicle: 5FNYF8H62PB007391

Main: (203)882-5686

2023 PASSH

BLACK

[NOEMAIL@EMAIL.COM](mailto:NOEMAIL@EMAIL.COM)

Cell:

Mileage: 28,432

Service advisor: 290

Tag number: T391

Payment type: CASH

Promised time: 08:00 PM

Promised date: 11/24/2025

Waiter: No

Estimate: 0.00

~~~~~  
A SAFETY CHECK & OIL AND FILTER CHANGE AND CHECK ALL FLUIDS  
SCLOF IUCN SAFETY CHECK & OIL AND FILTER CHANGE AND CHECK ALL FLUIDS N/C

Tech(s): 270  
15400PLMA02 1 OIL FILTER HONDA GENUINE N/C  
SOA635045 6 OIL 0W20 SYNTH N/C  
Pts: 0.00 Lbr: 0.00 Other: 0.00 Total Line A: 0.00  
~~~~~

B CUSTOMER STATES PERFORM ANY OPEN RECALL  
RECALL IUCN CUSTOMER STATES PERFORM ANY OPEN RECALL N/C

Tech(s): 270  
Pts: 0.00 Lbr: 0.00 Other: 0.00 Total Line B: 0.00  
~~~~~

C DMV SHEET  
DMV IUCN PASS N/C  
Tech(s): 270  
Pts: 0.00 Lbr: 0.00 Other: 0.00 Total Line C: 0.00  
~~~~~

D\*\* SUBARU CABIN AIR FILTER \$94.99  
CABIN IUCN SUBARU CABIN AIR FILTER \$94.99 N/C  
Tech(s): 270  
MISC 1 CABIN AIR FILTER (NAP) N/C  
Pts: 0.00 Lbr: 0.00 Other: 0.00 Total Line D: 0.00  
~~~~~

E\*\* SUBARU ENGINE AIR FILTER  
AIR IUCN SUBARU ENGINE AIR FILTER N/C  
Tech(s): 270  
MISC 1 ENGINE AIR FILTER (NAP) N/C  
Pts: 0.00 Lbr: 0.00 Other: 0.00 Total Line E: 0.00  
~~~~~

Customer Pay  
Labor 0.00  
Parts 0.00  
Lube 0.00  
Sublet 0.00  
Miscellaneous/Shop Charge 0.00  
Deductible 0.00

# Repair Order Detail - Customer Copy

Total Charges	0.00
Less Insurance/Adjustment	0.00
Sales Tax	0.00
Total	0.00