## Repair Order Detail - Customer Copy

RO Number: 461220 RO Status: CLOSED

Customer: DAN PERKINS SUBARU

NOEMAIL@EMAIL.COM

Phone(s): Contact: (203)882-5686

Main: (203)882-5686

Cell:

Vehicle: 4S4WMAHD4P3418805

2023 ASCE

**WHITE** 

Mileage: 38,700

Page 1, Created: 11/29/2025 02:03:56 PM

Payment type: CASH

Waiter: No

Service advisor: 290

Promised time: 08:00 PM

Estimate: 0.00

Tag number: T1052

Promised date: 11/17/2025

| ~-        | ~~~ | .~~~~~~~~~~~~~~~~        |                                                            | .~~~       |
|-----------|-----|--------------------------|------------------------------------------------------------|------------|
| Α         | 00  | IUC                      | CHECK PASS/MIRROR ASSY<br>INSTALLED NEW MIRROR<br>ASSY     | N/C        |
|           |     | Tech(s): 272             | A331                                                       |            |
|           |     | 91039FL03A               | 1 MIRROR REPAIR RH                                         | N/C        |
| Pts:      |     | 0.00 Lbr:                | 0.00 Other: 0.00 Total Line A:                             | 0.00       |
| B         | 511 |                          | VEHICLE HAS A PULSATION WHEN STOPPING  BOTH ROTORS R&R AND | N/C        |
|           | •   |                          | MEASURE RUNOUT 5 POSITIONS (BO                             | 14,0       |
|           |     | Tech(s): 272             | . 666 (26                                                  |            |
|           |     | 26296XC02A               | 1 PAD KIT F                                                | N/C        |
|           |     | 26300XC01A               | 2 PB002043 BRAKE DISC F                                    | N/C        |
|           |     | 26261XC000<br>26208XC000 | 2 TIE BAR<br>4 BOLT                                        | N/C<br>N/C |
| Pts:      |     | 0.00 Lbr:                | 0.00 Other: 0.00 Total Line B:                             | 0.00       |
| ~-        | ~~~ | .~~~~~~~~~               |                                                            | ~~~        |
| C**       |     | CUSTOMER STATES          |                                                            | N/O        |
|           | 00  | IUC                      | REPLACE THE REAR ROTORS FOR THE                            | N/C        |
|           |     |                          | PULSATION                                                  |            |
|           |     | Tech(s): 272             | 1 GEO/MIGIT                                                |            |
|           |     | 26700XC00A               | 2 BRAKE DISC R                                             | N/C        |
| Pts:      |     | 0.00 Lbr:                | 0.00 Other: 0.00 Total Line C:                             | 0.00       |
| ~~<br>D** | ~~~ | A WHEEL ALIGNMEN         | IT. INSPECT/ADJUST CASTER, CAMBER & TOE, INSPECT           | ~~~        |
| D         |     |                          | ERING. TECH ROAD TESTED.                                   |            |
|           | ALI | IGN IUC                  | 4 WHEEL ALIGNMENT.                                         | N/C        |
|           |     |                          | INSPECT/ADJUST                                             |            |
|           |     |                          | CASTER, CAMBER & TOE,                                      |            |
|           |     |                          | INSPECT SUSPENSION &                                       |            |
|           |     |                          | STEERING. TECH ROAD                                        |            |
|           |     | Tech(s): 272             | TESTED.                                                    |            |
| Pts:      |     | 0.00 Lbr:                | 0.00 Other: 0.00 Total Line D:                             | 0.00       |
| ~~        | ~~~ | ~~~~~~~~                 |                                                            | ~~~        |
| E**       | 00  | CUSTOMER STATES          | REPLACE ON LINE C                                          | N/C        |
|           |     | Tech(s): 272             |                                                            |            |
| Pts:      |     | 0.00 Lbr:                | 0.00 Other: 0.00 Total Line E:                             | 0.00       |
| ~~<br>F** | ~~~ | CUSTOMER STATES          |                                                            | ~~~        |
|           | 00  |                          | CUSTOMER STATES                                            | N/C        |
|           |     | Tech(s): 272             |                                                            | , 0        |
| _         |     |                          |                                                            |            |

## Repair Order Detail - Customer Copy

RO Status: CLOSED RO Number: 461220

Customer: DAN PERKINS SUBARU

NOEMAIL@EMAIL.COM

Phone(s): Contact: (203)882-5686

Main: (203)882-5686 Cell:

Vehicle: 4S4WMAHD4P3418805

2023 ASCE WHITE

Mileage: 38,700

Payment type: CASH

Waiter: No

Service advisor: 290 Tag number: T1052

Promised time: 08:00 PM Promised date: 11/17/2025 Estimate: 0.00

Pts: 0.00 Lbr: 0.00 Other: 0.00 Total Line F: 0.00

| Customer Pay              |      |
|---------------------------|------|
| Labor                     | 0.00 |
| Parts                     | 0.00 |
| Lube                      | 0.00 |
| Sublet                    | 0.00 |
| Miscellaneous/Shop Charge | 0.00 |
| Deductible                | 0.00 |
| Total Charges             | 0.00 |
| Less Insurance/Adjustment | 0.00 |
| Sales Tax                 | 0.00 |
| Total                     | 0.00 |