

Repair Order Detail - Customer Copy

RO Number: 458104

RO Status: CLOSED

Customer: DAN PERKINS SUBARU

Phone(s): Contact: (203)882-5686

Vehicle: 1N6AD0EV3CC472321

Main: (203)882-5686

2012 FRON

BLACK

NOEMAIL@EMAIL.COM

Cell:

Mileage: 100,329

Service advisor: 939

Tag number: T472321

Payment type: CASH

Promised time: 08:00 PM

Promised date: 10/03/2025

Waiter: No

Estimate: 0.00

~~~~~  
A SAFETY CHECK & OIL AND FILTER CHANGE AND CHECK ALL FLUIDS  
SCLOF IUCN SAFETY CHECK & OIL AND FILTER CHANGE AND CHECK ALL FLUIDS N/C

Tech(s): 87  
WIX57356 1 WIX OIL FILTER N/C  
SOA635044 6 OIL 5W30 SYNTH N/C  
OR 1 ORING N/C  
Pts: 0.00 Lbr: 0.00 Other: 0.00 Total Line A: 0.00  
~~~~~

B DMV SHEET
DMV IUC DMV SHEET PASS N/C

Tech(s): 87
Pts: 0.00 Lbr: 0.00 Other: 0.00 Total Line B: 0.00
~~~~~

C\*\* CUSTOMER STATES PASSENGER LEAF SPRINGS ARE BROKEN. CHECK AND ADVISE.  
OO IUCN TECH REMOVED AND REPLACED THE PASSENGER SIDE LEAF SPRING N/C

Tech(s): 87  
MISC 1 LEAF SPRING N/C  
Pts: 0.00 Lbr: 0.00 Other: 0.00 Total Line C: 0.00  
~~~~~

D** FRONT BRAKE SERVICE: PADS & ROTORS
FBJR IUCN FRONT BRAKE SERVICE: PADS & ROTORS N/C

Tech(s): 87
MISC 1 FRT PADS AND ROTORS N/C
Pts: 0.00 Lbr: 0.00 Other: 0.00 Total Line D: 0.00
~~~~~

E\*\* MOUNT AND BALANCE 4 TIRE  
MB4 IUCN MOUNT AND BALANCE 4 TIRE N/C

Tech(s): 87  
MISC 4 265/70R16 N/C  
WWT 1 WHEEL WEIGHT N/C  
Pts: 0.00 Lbr: 0.00 Other: 0.00 Total Line E: 0.00  
~~~~~

F** 4 WHEEL ALIGNMENT. INSPECT/ADJUST CASTER, CAMBER & TOE, INSPECT SUSPENSION & STEERING. TECH ROAD TESTED.
ALIGN IUCN 4 WHEEL ALIGNMENT. INSPECT/ADJUST CASTER, CAMBER & TOE, N/C

Repair Order Detail - Customer Copy

RO Number: 458104

RO Status: CLOSED

Customer: DAN PERKINS SUBARU

Phone(s): Contact: (203)882-5686

Vehicle: 1N6AD0EV3CC472321

Main: (203)882-5686

2012 FRON

BLACK

NOEMAIL@EMAIL.COM

Cell:

Mileage: 100,329

Service advisor: 939

Tag number: T472321

Payment type: CASH

Promised time: 08:00 PM

Promised date: 10/03/2025

Waiter: No

Estimate: 0.00

~~~~~  
INSPECT SUSPENSION &  
STEERING. TECH ROAD  
TESTED.

Tech(s): 87

Pts: 0.00 Lbr: 0.00 Other: 0.00 Total Line F: 0.00

~~~~~  
G** CUSTOMER STATES REMOVE AND REPLACE TIRE PRESSURE SENSORS.

OO IUCN TECH REMOVED AND
REPLACED ALL FOUR
TIRE PRESSURE SENORS N/C

Tech(s): 87

MISC

4 TPMS

Pts: 0.00 Lbr: 0.00 Other: 0.00 Total Line G: 0.00

~~~~~  
H\*\* FRONT WIPER REPLACEMENT (2X)

WIPER IUCN FRONT WIPER  
REPLACEMENT (2X) N/C

Tech(s): 87

SOA591U518

1 18" HYBRID WIPER BLADE

N/C

(P

SOA591U524

1 24" HYBRID WIPER BLADE

N/C

(D

Pts: 0.00 Lbr: 0.00 Other: 0.00 Total Line H: 0.00

~~~~~  
I** SUBARU ENGINE AIR FILTER

AIR IUCN SUBARU ENGINE AIR
FILTER N/C

Tech(s): 87

MISC

1 AIR FILTER

N/C

Pts: 0.00 Lbr: 0.00 Other: 0.00 Total Line I: 0.00

~~~~~  
Customer Pay

Labor 0.00

Parts 0.00

Lube 0.00

Sublet 0.00

Miscellaneous/Shop Charge 0.00

Deductible 0.00

Total Charges 0.00

Less Insurance/Adjustment 0.00

Sales Tax 0.00

Total 0.00