

Repair Order Detail - Customer Copy

RO Number: 473680

RO Status: CLOSED

Customer: DAN PERKINS SUBARU

Phone(s): Contact: (203)882-5686

Vehicle: 5NMJFCDE4SH600906

Main: (203)882-5686

2025 TUCS

NOEMAIL.EMAIL@EMAIL.COM

Cell: (203)882-5686

Mileage: 6,998

Service advisor: 580

Tag number: T0906UC

Payment type: CASH

Promised time: 08:00 PM

Promised date: 05/30/2026

Waiter: No

Estimate: 0.00

~~~~~  
A SAFETY CHECK & OIL AND FILTER CHANGE AND CHECK ALL FLUIDS  
SCLOF IUCN SAFETY CHECK & OIL N/C  
AND FILTER CHANGE AND  
CHECK ALL FLUIDS

Tech(s): 963

MISC

1 OIL FILTER

N/C

SOA635045

6 OIL 0W20 SYNTH

N/C

OR

1 ORING

N/C

Pts: 0.00 Lbr: 0.00 Other: 0.00 Total Line A: 0.00  
~~~~~

B DMV SHEET
DMV IUCN DMV SHEET N/C

Tech(s): 963

Pts: 0.00 Lbr: 0.00 Other: 0.00 Total Line B: 0.00
~~~~~

C\*\* PERFORM TIRE ROTATION  
TR IUCN PERFORM TIRE ROTATION N/C

Tech(s): 963

Pts: 0.00 Lbr: 0.00 Other: 0.00 Total Line C: 0.00  
~~~~~

Customer Pay

Labor 0.00

Parts 0.00

Lube 0.00

Sublet 0.00

Miscellaneous/Shop Charge 0.00

Deductible 0.00

Total Charges 0.00

Less Insurance/Adjustment 0.00

Sales Tax 0.00

Total 0.00