

# Repair Order Detail - Customer Copy

RO Number: 469369

RO Status: CLOSED

Customer: DAN PERKINS SUBARU

[NOEMAIL.EMAIL@EMAIL.COM](mailto:NOEMAIL.EMAIL@EMAIL.COM)

Phone(s): Contact: (203)882-5686

Main: (203)882-5686

Cell: (203)882-5686

Vehicle: JF1GUABC8S8332326

2025 IMPR

GRAY

Mileage: 2,724

Payment type: CASH

Waiter: No

Service advisor: 290

Promised time: 08:00 PM

Estimate: 0.00

Tag number: T326

Promised date: 03/27/2026

~~~~~  
**A SAFETY CHECK & OIL AND FILTER CHANGE AND CHECK ALL FLUIDS**  
 SCLOF IUC SAFETY CHECK & OIL N/C  
 AND FILTER CHANGE AND  
 CHECK ALL FLUIDS

Tech(s): 98  
 15208AA21A 1 ELEM CP-OIL FLTR N/C  
 SOA635335 5 0W-16 SYNTHETIC MOTOR N/C  
 OIL  
 803916010 1 GASKET N/C

Pts: 0.00 Lbr: 0.00 Other: 0.00 Total Line A: 0.00  
 Story: 2724 PERFORM LUBE OIL AND FILTER CHANGE WITH GENUINE  
 SUBARU PARTS AND FLUIDS

~~~~~  
**B DMV SHEET**  
 DMV IUC PASS N/C

Tech(s): 98  
 Pts: 0.00 Lbr: 0.00 Other: 0.00 Total Line B: 0.00

~~~~~  
**C NO OPEN RECALL AS OF TODAY**  
 NR IUC NO OPEN RECALL AS OF N/C  
 TODAY

Tech(s): 98  
 Pts: 0.00 Lbr: 0.00 Other: 0.00 Total Line C: 0.00

~~~~~  
**D CERTIFIED PRE-OWNED VEHICLE INSPECTION**  
 CPO IUC CERTIFIED PRE-OWNED N/C  
 VEHICLE INSPECTION

Tech(s): 98  
 Pts: 0.00 Lbr: 0.00 Other: 0.00 Total Line D: 0.00

~~~~~  
 Customer Pay  
 Labor 0.00  
 Parts 0.00  
 Lube 0.00  
 Sublet 0.00  
 Miscellaneous/Shop Charge 0.00  
 Deductible 0.00  
 Total Charges 0.00  
 Less Insurance/Adjustment 0.00  
 Sales Tax 0.00  
 Total 0.00