

West Coast Ford Lincoln



Vehicle Condition Report

Prepared on February 6, 2020 for:

CHARLES DUNSMORE
Service Advisor

WEST COAST FORD LINC

20370 Lougheed Hwy
MAPLE RIDGE , BC V2X 2P8
(604) 465-5434
C-DUNS@SHAW.CA

Vehicle: **2009 FORD TRUCK ESCAPE**

VIN: **1FMCU03G79KA98144**

License:

Odometer: **156,975**

RO: **171949**

We appreciate you choosing us for your service needs! If you need assistance email our Service Department at service@westcoastfordlincoln.com



West Coast Ford Report Card


Customer Name: WEST COAST FORD LINCOLN Vehicle Year/Model: 09 FORD TRUCK ESCAPE Date/Time: 02/06/2020 13:45:30
 Phone: (H) (604) 465-5434 VIN: 1FMCU03G79KA98144 Odometer: 156975
 Service Advisor: CHARLES DUNSMORE Technician: DAN GRAY RO: 171949 Tag: 8144

INSPECTION RESULT - OK	WILL REQUIRE FURTHER ATTENTION	REQUIRES IMMEDIATE ATTENTION
-------------------------------	---------------------------------------	-------------------------------------

Green Yellow Red Served

<input checked="" type="checkbox"/> Green	<input type="checkbox"/> Yellow	<input type="checkbox"/> Red	Fill windshield washer fluid	<input type="checkbox"/>
<input checked="" type="checkbox"/> Green	<input type="checkbox"/> Yellow	<input type="checkbox"/> Red	Inspect wipers/washers including front and rear blades	<input type="checkbox"/>
<input checked="" type="checkbox"/> Green	<input type="checkbox"/> Yellow	<input type="checkbox"/> Red	Inspect exterior lamps/lights/bulbs (operation/damage)	<input type="checkbox"/>
<input checked="" type="checkbox"/> Green	<input type="checkbox"/> Yellow	<input type="checkbox"/> Red	Warning lights	<input type="checkbox"/>
<input checked="" type="checkbox"/> Green	<input type="checkbox"/> Yellow	<input type="checkbox"/> Red	Inspect dash lights/interior lights/horn operation	<input type="checkbox"/>
<input checked="" type="checkbox"/> Green	<input type="checkbox"/> Yellow	<input type="checkbox"/> Red	Interior	<input type="checkbox"/>
<input checked="" type="checkbox"/> Green	<input type="checkbox"/> Yellow	<input type="checkbox"/> Red	Inspect air cleaner element	<input type="checkbox"/>
<input checked="" type="checkbox"/> Green	<input type="checkbox"/> Yellow	<input type="checkbox"/> Red	Inspect cabin air filter (if equipped)	<input type="checkbox"/>
<input checked="" type="checkbox"/> Green	<input type="checkbox"/> Yellow	<input type="checkbox"/> Red	Inspect drive belts and hoses	<input type="checkbox"/>
<input checked="" type="checkbox"/> Green	<input type="checkbox"/> Yellow	<input type="checkbox"/> Red	Inspect battery terminals and cables	<input type="checkbox"/>
<input checked="" type="checkbox"/> Green	<input type="checkbox"/> Yellow	<input type="checkbox"/> Red	Check brake fluid level and condition	<input type="checkbox"/>
<input checked="" type="checkbox"/> Green	<input type="checkbox"/> Yellow	<input type="checkbox"/> Red	Check engine coolant level and condition	<input type="checkbox"/>
<input checked="" type="checkbox"/> Green	<input type="checkbox"/> Yellow	<input type="checkbox"/> Red	Check power steering fluid level and condition	<input type="checkbox"/>
<input checked="" type="checkbox"/> Green	<input type="checkbox"/> Yellow	<input type="checkbox"/> Red	Check transmission fluid level and condition (most models)	<input type="checkbox"/>
<input checked="" type="checkbox"/> Green	<input type="checkbox"/> Yellow	<input type="checkbox"/> Red	Under hood	<input type="checkbox"/>
<input checked="" type="checkbox"/> Green	<input type="checkbox"/> Yellow	<input type="checkbox"/> Red	Inspect front /rear differential and transfer case (leaks)	<input type="checkbox"/>
<input checked="" type="checkbox"/> Green	<input type="checkbox"/> Yellow	<input type="checkbox"/> Red	Inspect exhaust system (leaks/damage/loose parts)	<input type="checkbox"/>
<input checked="" type="checkbox"/> Green	<input type="checkbox"/> Yellow	<input type="checkbox"/> Red	Inspect brake system components (leaks/wear/damage)	<input type="checkbox"/>
<input checked="" type="checkbox"/> Green	<input type="checkbox"/> Yellow	<input type="checkbox"/> Red	Inspect steering system (leaks/wear/damage)	<input type="checkbox"/>
<input checked="" type="checkbox"/> Green	<input type="checkbox"/> Yellow	<input type="checkbox"/> Red	Inspect cooling system (leaks/wear/damage)	<input type="checkbox"/>
<input checked="" type="checkbox"/> Green	<input type="checkbox"/> Yellow	<input type="checkbox"/> Red	Inspect heating and air conditioning operation	<input type="checkbox"/>
<input checked="" type="checkbox"/> Green	<input type="checkbox"/> Yellow	<input type="checkbox"/> Red	Inspect front suspension	<input type="checkbox"/>
<input checked="" type="checkbox"/> Green	<input type="checkbox"/> Yellow	<input type="checkbox"/> Red	Inspect rear suspension	<input type="checkbox"/>
<input checked="" type="checkbox"/> Green	<input type="checkbox"/> Yellow	<input type="checkbox"/> Red	Inspect axles/driveshaft(s)/U-joints/CV joints/boots	<input type="checkbox"/>
<input checked="" type="checkbox"/> Green	<input type="checkbox"/> Yellow	<input type="checkbox"/> Red	Inspect transmission for leaks	<input type="checkbox"/>
<input checked="" type="checkbox"/> Green	<input type="checkbox"/> Yellow	<input type="checkbox"/> Red	Inspect engine (leaks/wear/damage)	<input type="checkbox"/>
<input checked="" type="checkbox"/> Green	<input type="checkbox"/> Yellow	<input type="checkbox"/> Red	Inspect fuel tank/lines/connections	<input type="checkbox"/>
<input checked="" type="checkbox"/> Green	<input type="checkbox"/> Yellow	<input type="checkbox"/> Red	Time/mileage requirements	<input type="checkbox"/>

Front / Rear Brake Linings


LF		RF
<input checked="" type="checkbox"/> Green		<input type="checkbox"/> Green
<input checked="" type="checkbox"/> Yellow		<input checked="" type="checkbox"/> Yellow
<input type="checkbox"/> Red		<input type="checkbox"/> Red
LR		RR
<input checked="" type="checkbox"/> Green		<input checked="" type="checkbox"/> Green
<input type="checkbox"/> Yellow		<input type="checkbox"/> Yellow
<input type="checkbox"/> Red		<input type="checkbox"/> Red

(See Note)

Inspection Not Taken

More than 6mm
3mm to 5mm
2mm or less


Check Tires / Tread Depth

LF		RF
<input checked="" type="checkbox"/> Green		<input checked="" type="checkbox"/> Green
<input type="checkbox"/> Yellow		<input type="checkbox"/> Yellow
<input type="checkbox"/> Red		<input type="checkbox"/> Red
LR		RR
<input checked="" type="checkbox"/> Green		<input checked="" type="checkbox"/> Green
<input type="checkbox"/> Yellow		<input type="checkbox"/> Yellow
<input type="checkbox"/> Red		<input type="checkbox"/> Red

7/32" or Greater
4/32" to 6/32"
3/32" or Less

Brake Inspection Comment: Rear: REAR DRUM BRAKES
Brake Lining Measurements: LF: 5 mm RF: 5 mm LR: 2 mm RR: 2 mm
Tire Tread Measurements: LF: 11/32" RF: 11/32" LR: 11/32" RR: 11/32"
Tire Pressure Measurements: LF: 32psi RF: 32psi LR: 32psi RR: 32psi

Check Battery Performance

	<input checked="" type="checkbox"/> Good <input type="checkbox"/> Fair <input type="checkbox"/> Bad
Actual Cold Cranking Amps	506
Factory Cold Cranking Amps	500

Repair Estimate

Printed Date: February 6, 2020

We have performed our multi-point inspection on your vehicle and the following services were recommended.

EXISTING SERVICES

Job	Quote
THE WORKS PERFORM "THE WORKS" SERVICE. CHANGE ENGINE OIL AND FILTER COM	123.36
WASH & VAC COMPLIMENTARY WASH AND VACUUM IF TIME PERMITS Y / N	0.00
VEHICLE REPORT CARD PERFORM VEHICLE REPORT CARD MULTI POINT INSPECTION AND REPO	0.00
Existing Services Total	\$ 123.36

SUGGESTED SERVICES

Job	Quote																																													
YELLOW FRONT BRAKES ATTENTION SOON FRONT BRAKES MAY NEED ATTENTION NEXT VISIT	378.43																																													
<table border="1"> <thead> <tr> <th>Qty</th> <th>Part Number</th> <th>Part Description</th> <th>Price</th> <th>Ext Price</th> </tr> </thead> <tbody> <tr> <td>1.00</td> <td>BR-1047-D</td> <td>KIT - BRAKE LI</td> <td>106.99</td> <td>106.99</td> </tr> <tr> <th>Misc Code</th> <th>Misc Description</th> <th></th> <th></th> <th>Ext Price</th> </tr> <tr> <td>SS</td> <td>SHOP SUPPLIES</td> <td></td> <td></td> <td>20.97</td> </tr> <tr> <td></td> <td></td> <td>Labor 1.50 Hrs</td> <td></td> <td>209.93</td> </tr> <tr> <td></td> <td></td> <td>Parts</td> <td></td> <td>106.99</td> </tr> <tr> <td></td> <td></td> <td>Misc</td> <td></td> <td>20.97</td> </tr> <tr> <td></td> <td></td> <td>Tax</td> <td></td> <td>40.54</td> </tr> <tr> <td></td> <td></td> <td>Total</td> <td></td> <td>378.43</td> </tr> </tbody> </table>	Qty	Part Number	Part Description	Price	Ext Price	1.00	BR-1047-D	KIT - BRAKE LI	106.99	106.99	Misc Code	Misc Description			Ext Price	SS	SHOP SUPPLIES			20.97			Labor 1.50 Hrs		209.93			Parts		106.99			Misc		20.97			Tax		40.54			Total		378.43	
Qty	Part Number	Part Description	Price	Ext Price																																										
1.00	BR-1047-D	KIT - BRAKE LI	106.99	106.99																																										
Misc Code	Misc Description			Ext Price																																										
SS	SHOP SUPPLIES			20.97																																										
		Labor 1.50 Hrs		209.93																																										
		Parts		106.99																																										
		Misc		20.97																																										
		Tax		40.54																																										
		Total		378.43																																										
Suggested Services Total	\$ 378.43																																													
Total Estimate	\$ 501.79																																													



RECOMMENDED NOT DONE

These items were recommended by our certified Ford Technician but not completed during this visit.

All estimates are good for 30 days from time of estimate.

